DAIMLER

10V-472 (2 pages)

Daimler Trucks North America Nasser Zamani Senior Manager Compliance and Regulatory Affairs

October 7, 2010

Dan Smith
Associate. Administrator for Enforcement
National Highway Traffic Safety Administration
Attention: Recall Management Division (NVS-215)
1200 New Jersey Avenue S.E.
Washington D.C. 20590

Re: Defect Information Report 10C-6, MBE 900 Reprogramming

Mr. Smith

In accordance with Part 573 of Title 49 of the Code of Federal Regulations, Daimler Trucks North America LLC herewith reports a safety campaign to recall approximately 2,935 Thomas Built Buses Saf-T-Liner C2 and Saf-T-Liner HDX school busses and approximately 62 Freightliner Business Class M2, Freightliner Custom Chassis Corporation MT45 Chassis and S2 Chassis, and Sterling Acterra vehicles manufactured October 5,2006 through May 24, 2010, and equipped with an EPA 2007 MBE 900 engine with a defect in engine control software.

Attached is Daimler Trucks North America's Defect Information Report.

Please contact me if you have any questions.

Sincerely ours,

Wasser Zamani

Cc: Michael Mason, CAL-OSHA

Enclosure

Certified Mail# 7006 3450 0000 3866'7966

Nasser.ZamanlBDaimler.com

DAIMLER

Defect Information Report

(Section 573.6)

Date: October 7,2010

Daimler Trucks North America LLC (c)(1) Manufacturer:

P.O. BOX 3849

Portland, Oregon 97208

(503) 745-5219

Brands: Freightliner, Freightliner Custom Chassis Corporation, Sterling

Vehicles identification: (c)(2)

Model(s) affected: Freightliner Business Class M2

Freightliner Custom Chassis MT45 Chassis and S2 Chassis

Sterling Acterra

Model Years affected: 2007,2008,2009,2010 Manufacture Dates: October 5,2006 through May 12,2010

Basis for determining population: All bus and emergency vehicles containing EPA 2007

MBE 900 engines manufactured October 18,2006 through July 24,2009 Component manufacturer if other than the vehicle manufacturer:

Detroit Diesel Corporation, C/o Daimler Trucks North America LLC

- Total number of vehicles potentially affected: Approximately 62 (c)(3)
- (c)(4)Percentage of vehicles estimated to contain the defect: 100%
- Description of the defect: Engine software may not react properly to certain aftertreatment (c)(5)device fault codes. The software may unnecessarily shutdown a vehicle or may fail to shutdown a vehicle with an aftertreatment device over-temp fault.
 - **49CFR** Section **577.5(f)** Evaluation of the risk to motor vehicle safety: Unexpected shutdown of a vehicle may not allow the driver to completely exit the roadway increasing the risk of a crash and overheating of the aftertreatment device without engine shutdown may result in a fire.
- Chronology of principal events: Information will be submitted as a supplemental report when (c)(6)available.
- (c)(7) Noncompliance-test or other data: N/A
- (i)Remedial program: The vehicle engine software will be updated. Repairs will be performed (c)(8)by Detroit Diesel Corporation (DDC) Authorized Repair Facilities. Reimbursement Plan: Copies will be submitted as a supplemental report when available.
 - (ii) Estimated Owner and Dealer Notification Date: Customer notification will be by first class mail using Daimler Trucks North America records to determine the customers affected. This will be completed approximately TBD Dealer and distributor notification, will be completed approximately TBD
- (c)(9) Information for tire recalls: Not Applicable
- (c)(10) Communications sent to manufacturers, dealers and owners: Copies will be submitted as a supplemental report when available.
- (c)(11) Manufacturer's campaign number: 10C-6