

On-scene Investigation / Vehicle to Vehicle
Dynamic Science, Inc. / Case Number: DS01007
2001 Mercury Sable
Kansas
January, 2001

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

Technical Report Documentation Page

1. Report No. DS01007		2. Government Accession No.		3. Recipient Catalog No.	
4. Title and Subtitle In-Depth Accident Investigation				5. Report Date	
				6. Performing Organization Report No.	
7. Author(s) Dynamic Science, Inc.				8. Performing Organization Report No.	
9. Performing Organization name and Address Dynamic Science, Inc. 530 College Parkway, Ste. K Annapolis, MD 21401				10. Work Unit No. (TRAIS)	
				11. Contract or Grant no. DTNH22-94-D-27058	
12. Sponsoring Agency Name and Address U.S. Dept. of Transportation (NRD-32) National Highway Traffic Safety Administration 400 7th Street, SW Washington, DC 20590				13. Type of report and period Covered [Report Month, Year]	
				14. Sponsoring Agency Code	
15. Supplemental Notes					
16. Abstract <p>This case was initiated because the case vehicle was equipped with Advanced Occupant Protection System features. The collision occurred in Kansas in January, 2001 at 1703 hours. This was a two vehicle angle/broadside type collision at the intersection of a heavily congested entrance/exit to a strip mall and surface street. The case vehicle is a 2001 Mercury Sable that was driven by an unrestrained 20-year-old female. The 2nd seat left position was occupied by an unrestrained 3-year-old male child. The case vehicle was traveling eastbound in the left through lane. The other vehicle, a 1971 Plymouth Road Runner driven by a 16-year-old male, was exiting the driveway traveling north and attempting a left turn to head west. As the Plymouth was in the middle of the intersection, the front (01FDEW1) of the case vehicle struck the front left (10LFEW3) of the Plymouth. On impact, the front air bags in the case vehicle deployed. After impact, the case vehicle rotated slightly counterclockwise and the Plymouth rotated clockwise. There was a second impact with the right side (03RZEW2) of the case vehicle side-slapping the rear left (09LBEW2) of the Plymouth. Both vehicles were towed from the scene due to damage.</p> <p>The police were notified of the collision at 1705 hours and arrived at the scene at 1710 hours. The local fire department EMS were notified and they arrived on scene treated and transported the injured to a local hospital where they were treated and released.</p> <p>The driver of the case vehicle sustained an abrasion to her left palm and a right ankle fracture.</p>					
17. Key Words Air bag, deployment, injury, accident, AOPS, advanced, rental, fleet, passenger,			18. Distribution Statement		
19. Security Classif. (of this report)		20. Security Classif. (of this page)		21. No of pages	22. Price

Dynamic Science, Inc.
Accident Investigation
Case Number: DS01007

TABLE OF CONTENTS

Background 1
 Description 1
 Investigation Type 1
 Crash Location 1
 Crash Date 1
 Notification Date 1
 Field Work Completed 1

Summary 1

Scene Diagram 4

Detailed Information 5
 Vehicles 5
 AOPS Discussion 6
 Occupants 9
 Injuries and Injury Mechanisms 11
 Occupant Kinematics 12

Attachment 1. EDR Readout 13

BACKGROUND:

Description: This Advanced Occupant Protection System case was reported to the NHTSA by DSI on March 28, 2001 and the case was assigned to DSI on March 30, 2001. An on-site investigation was conducted and all field work was completed on April 4, 2001.

Investigation Type: On scene

Crash Location: Kansas

Crash Date: January, 2001

Notification Date: March 30, 2001

Field Work Completed: April 4, 2001

SUMMARY:

The collision occurred in Kansas in January, 2001 at 1703 hours. This was a two vehicle angle/broadside type collision at the intersection of a heavily congested entrance/exit to a strip mall and surface street. The eastbound roadway consists of a right turn lane into the strip mall, two through travel lanes and a left turn lane. East and west traffic are separated by a raised concrete center median. The westbound roadway consists of two through travel lanes and a left turn lane. At the point of impact, the eastbound roadway surface is straight and level. There are no traffic controls and the speed limit for east and westbound traffic is 56 km/h (35 mph). The driveway consists of three lanes. Northbound traffic is exiting the strip mall and there is a left or through travel lane and right turn only lane. The third lane is entering the strip mall in a southerly direction. Northbound traffic is controlled by a standard stop sign and the speed limit is 40 km/h (25 mph). The weather was clear and the asphalt road surface was dry.



Figure 1. Direction of travel for case vehicle towards the impact area (east).

The case vehicle is a 2001 Mercury Sable that was driven by an unrestrained¹ 20-year-old female. This was a rental vehicle. The 2nd seat left position was occupied by an unrestrained 3-year-old male child. The case vehicle was traveling eastbound in the left through lane. The other vehicle, a 1971 Plymouth Road Runner driven by a 16-year-old male, was exiting the driveway traveling north and attempting a left turn to head west. As the Plymouth was in the middle of the intersection, the front (01FDEW1) of the case vehicle struck the front left (10LFEW3) of the Plymouth. On impact, the front air bags in the case vehicle deployed. The case vehicle sustained a total delta v of 18.2 km/h (11.3 mph), a longitudinal delta v of -15.8 km/h (-9.8 mph), and a latitudinal delta v of -9.1 km/h (-5.7 mph)². The downloaded Electronic Data Recorder (EDR) data indicates a cumulative longitudinal delta v of -24.9 km/h (-15.5 mph) and a cumulative lateral delta v of -14 km/h (-8.7 mph) at the 78 ms mark. The EDR report is included as an attachment to this report.

The Plymouth sustained a delta v of 16.3 km/h (10.1 mph), a longitudinal delta v of -6.9 km/h (-4.3 mph), and a latitudinal delta v of 14.8 km/h (9.2 mph). The WinSmash results fit the collision model for both vehicles and appear reasonable for the case vehicle but borderline for the Plymouth.



Figure 2. Front, case vehicle



Figure 3. Second impact-side slap to case vehicle.

¹ The police report indicates that she was restrained by the available lap and shoulder belt. Measurement of the pretensioner barrel indicates that it did not fire and therefore the lap and shoulder belt was not engaged.

² Calculated using the damage only algorithm of Winsmash 1.2.1 and stiffness values for the case vehicle calculated using NCAP crash data. CDC for Plymouth estimated from insurance photographs.

After impact, the case vehicle rotated slightly counterclockwise and the Plymouth rotated clockwise. There was a second impact with the right side (03RZEW2) of the case vehicle side-slapping the rear left (09LBEW2) of the Plymouth. The case vehicle sustained a latitudinal delta v of -11.5 km/h (-7.1 mph).

Both vehicles were towed from the scene due to damage.

The police were notified of the collision at 1705 hours and arrived at the scene at 1710 hours. The local fire department EMS were notified and they arrived on scene treated and transported the injured to a local hospital where they were treated and released.



Figure 4. Exterior damage to Plymouth.

The driver of the case vehicle sustained an abrasion to her left palm and a right ankle fracture.

The police report indicates that the driver and 3-year-old in the case vehicle sustained “possible injuries”. The police report further indicated that the driver was treated for a possible fractured right ankle. The 3-year-old was treated for minor back pain and released.

The driver of the Plymouth also sustained “possible injuries”. He was treated at the scene by EMS personnel and released without transporting.

Scene Diagram




Figure 5. Scene diagram

DETAILED INFORMATION

Vehicles

Case vehicle

Description:	2001 Mercury Sable four door sedan (rental)	
VIN:	1MEFM50U91Gxxxxxx	
Odometer:	2,242 km (1,393 miles)	
Engine:	3.0 L (182 CID), 6 cylinder	
Reported Defects:	None	
Cargo:	None	
Damage Description:	Moderate frontal damage to bumper, grille, and hood. Moderate side slap damage to right side above right tire and extending across right rear door.	
CDC:	Impact 1: 01FDEW1 Impact 2: 03RZEW2	
Delta V (Impact 1):	Total	18.2 km/h (11.3 mph)
	Longitudinal	-15.8 km/h (-9.8 mph)
	Latitudinal	-9.1 km/h (-5.7 mph)
	Energy	22,769 joules (16,791 ft-lbs)



Figure 6. Front right, case vehicle

AOPS Discussion

This vehicle was equipped with advanced occupant protection system features. The system consists of a Restraint Control Module (RCM), dual stage front air bags, seat belt pretensioners, seat track sensors, and seat belt latch usage detectors. The system is controlled by the RCM. The primary function of the RCM is to control the deployment of the occupant protection systems. The system records longitudinal and lateral acceleration. Data related to the driver and passenger air bag deployment include: 78 milliseconds of crash pulse, deployment strategy of the dual-stage air bag system, seat belt latch use, pretensioner operation, and driver seat track location.



Figure 7. Front air bags

At impact the case vehicle sustained a total Δv of 18.2 km/h (11.3 mph), a longitudinal Δv of -15.8 km/h (-9.8 mph) and a latitudinal Δv of -9.1 km/h (-5.7 mph) as computed by WinSmash. The downloaded Electronic Data Recorder (EDR) data indicates a cumulative longitudinal Δv of -24.9 (-15.5 mph) and a cumulative lateral Δv of -14 km/h (-8.7 mph) at the 78 ms mark.

The EDR report further indicates that:

1. This was a first stage deployment. The second stage was purged for disposal.
2. The driver's seat was not in the forward position.
3. The left front and right front seat buckles were not engaged.
4. The time from algorithm wake-up to pretensioner was 10 milliseconds
5. The time from algorithm wake-up to first stage - unbelted was 19 milliseconds.

Both front seat positions of the case vehicle were equipped with seat belt pretensioners. The pretensioner barrels were measured. The driver's pretensioner measured 11.1 cm (4.4 in.)-indicating that it had not fired. The passenger's pretensioner measured 11.0 cm (4.3 in.)-indicating that it had not fired. The right shear capsule stroke measured 0.9 cm (0.4 in.) and 0.4 cm (0.2 in.) to the left shear capsule. The steering column breakaway coupling was intact.

The case vehicle was equipped with a driver's and front right passenger's air bags. The driver's steering wheel mounted air bag was circular and measured 45 cm (17.7 in.) in diameter. It was equipped with two tethers and two vent holes. There was no evidence of driver contact although she possibly did contact the air bag. The dual module covers opened in a typical "H" configuration. There

were no indications of any damage to the covers. The front right passenger's top mounted air bag was rectangular and measured 61 cm (24.0 in.) by 48 cm (18.9 in.). It was equipped with two vent ports and did not have any tethers. On the face of the air bag there was cover-related scuffing. The single flap module cover did not sustain any damage.

Other vehicle

Description:	1971 Plymouth Road Runner	
VIN:	RM23N1Rxxxxxx	
Odometer:	139,210 km (86,504 miles)	
Engine:	383 CID V8	
Reported Defects:	None	
Cargo:	Unknown	
Damage Description:	Moderate lateral crush to left front fender and tire. Minor side slap damage to the left rear quarter panel.	
CDC:	Impact 1: 10LFEW3 Impact 2: 09LBEW2	
Delta V (Impact 1):	Total	16.3 km/h (10.1 mph)
	Longitudinal	-6.9 km/h (-4.3 mph)
	Latitudinal	14.8 km/h (9.2 mph)
	Energy	34,977 joules (25,824 ft-lbs)

Occupants

<u>Case vehicle</u>	Occupant 1	Occupant 2
Age/Sex:	20/Female	3/Male
Seated Position:	Front left	Second row, left
Seat Type:	Fabric covered bucket seat—seat track adjusted to the rear most position	Fabric covered bench seat
Height:	163 cm (64 in)	107 cm (42 in)
Weight:	74.8 kg (165 lbs)	14.9 kg (33 lbs)
Occupation:	Unknown	NA
Pre-existing Medical Condition:	None noted	None noted
Alcohol/Drug Involvement:	None	None
Driving Experience:	Unknown	NA
Body Posture:	Normal, upright	Normal, upright
Hand Position:	Both hands on steering wheel	Unknown
Foot Position:	Left foot on floor board, right on brake	Unknown
Restraint Usage:	Lap and shoulder belt available, not used	Lap and shoulder belt available, not used
Air bag:	Steering wheel mounted driver air bag deployed	NA

<u>Other vehicle</u>	Driver
Age/Sex:	16/Male
Seated Position:	Front left
Seat Type:	Leather covered bucket seat
Height:	Unknown
Weight:	Unknown
Occupation:	Unknown
Pre-existing Medical Condition:	None noted
Alcohol/Drug Involvement:	None
Driving Experience:	Minimal, likely less than 1 year
Body Posture:	Unknown
Hand Position:	Unknown
Foot Position:	Unknown
Restraint Usage:	Lap and shoulder belt used, per police report

Injuries and Injury MechanismsCase vehicle

	<u>INJURY</u>	<u>OIC CODE</u>	<u>ICD-9</u>	<u>SOURCE</u>
Driver:	Abrasion, palm of right hand	790202.1,1	914.0	Air bag
	Fractured right ankle	852002.2,1	824.9	Floor board
Left rear occupant:	No coded injuries. Complained of back pain.			

Other vehicle

Driver:	No reported injuries.
---------	-----------------------

Occupant Kinematics

The driver of the case vehicle was seated in a normal, upright fashion. She was not wearing the available lap and shoulder belt. The upper anchorage adjustment was in the up position. The fabric-covered bucket seat was adjusted to the rear most track position, and the seat back angle was adjusted to a rearward reclined position of 17E. Prior to impact, the driver began braking with her right foot. At impact, the unrestrained driver responded to the 1 o'clock direction of force by moving forward and to the right. Her face probably came into contact with the deploying air bag even though there was no evidence of contact. Both of her legs struck the left instrument panel causing damage to the rigid plastic cover and slight deformation to the left knee bolster. The deploying air bag contacted her right palm—causing a minor abrasion. Her right foot came off the brake to the right and contacted the floor board—causing an ankle fracture. She responded to the 3 o'clock side-slap by moving to the right and possibly struck the center arm rest/seat area.



The 3-year-old rear left occupant was seated in the 2nd seat left position and he was unrestrained. At impact, he responded to the 1 o'clock direction of force by moving forward and to the right. He probably struck the driver's seat back. He responded to the 3 o'clock side-slap by moving to the right.

Attachment 1. EDR readout

Investigation Data

File Name:	DS01-007.hex	File Save Date:	06-Apr-2001
File Read-out Date:	N/A	Report Date:	06-Apr-2001
Report Version:	1.6		

EDR Control Module Data

Data Validity Check:	Valid	EDR Model Version:	141
Time From Side Saling Decision to Left (Driver) Side Bag Deployment:	Not Deployed		
Time From Side Saling Decision to Right (Passenger) Side Bag Deployment:	Not Deployed		
Passenger Airbag Switch Position During Event:	N/A		
Diagnostic Codes Active When Event Occurred:	0		

Algorithm Times

Actual initiation depends on restraint system status (below).

	ms
Time From Algorithm Wakeup to Pretensioner:	10
Time From Algorithm Wakeup to First Stage - Unbelted:	19
Time From Algorithm Wakeup to First Stage - Belted:	23
Time From Algorithm Wakeup to Second Stage:	0

Restraint System Status

Driver Seat Belt Buckle:	Not Engaged
Passenger Seat Belt Buckle:	Not Engaged
Driver Seat Track In Forward Position:	No
Passenger Seat Weight Switch Position:	N/A


Deployment Initiation Attempt Times

	Driver	Passenger
Time From Algorithm Wakeup to Pretensioner Deployment Attempt:	Unbelted	Unbelted
Time From Algorithm Wakeup to First Stage Deployment Attempt:	19	19
Time From Algorithm Wakeup to Second Stage Deployment Attempt:	Disposal	Disposal

Longitudinal Cumulative Delta-V

Time (ms)	0	10	20	30	40	50	60	70	78
Delta-V (MPH)									


Note: Acceleration data and plots are only valid for frontal impact event recordings.



Lateral Cumulative Delta-V

Time (ms)	0	10	20	30	40	50	60	70	78
Delta-V (MPH)	0	0	0	0	0	0	0	0	0

Note: Acceleration data and plots are only valid for frontal impact event recordings.



File Name: DS01-007.hex

Hexidecimal Module Memory Dump

Address	00	01	02	03	04	05	06	07	08	09	0A	0B	0C	0D	0E	0F
0800	11	4A	40	76	14	FB	77	77	77	77	0E	24	0F	2B	1A	57
0810	0E	FF	00	FF	52	60	52	60	60	52	ED	20	3C	7B	D6	AD
0820	06	01	26	17	5F	0E	0F	0A	75	0A	ED	64	A1	5E	C9	95
0830	03	0C	1B	1E	00	77	2C	2C	90	06	28	64	64	00	0C	01
0840	5A	94	50	77	77	77	87	87	D8	E7	77	71	4E	11	25	81
0850	8C	14	09	0F	01	77	77	74	7F	77	CD	44	06	77	77	9E
0860	77	77	77	77	77	77	77	77	77	77	77	77	77	77	77	77
0870	06	1E	47	AB	E7	00	87	87	59	46	31	41	00	04	77	19
0880	03	7C	80	12	8C	80	06	77	7D	18	77	80	09	77	8D	77
0890	0A	77	80	0F	77	80	12	77	80	77	77	00	77	77	00	77
08A0	44	94	0C	00	00	00	00	01	00	00	77	77	77	77	77	77
08B0	01	77	81	1B	00	8D	01	77	77	77	77	77	28	01	ED	78
08C0	77	14	81	ED	77	52	01	ED	77	04	10	61	79	72	77	7E
08D0	03	0E	0C	8D	02	56	16	97	1F	8E	01	0A	00	8C	01	04
08E0	00	70	01	16	00	80	01	54	00	1F	02	10	01	C7	02	8A
08F0	06	14	07	08	01	2C	03	0A	04	CE	06	40	73	13	00	AD
0900	1F	77	80	03	00	4B	01	CC	00	03	0F	77	00	14	00	7B
0910	00	AC	00	8E	0A	16	77	01	00	00	00	77	0F	DC	0F	02
0920	03	5A	12	4E	05	50	02	02	7A	1E	08	9C	0A	1C	02	23
0930	06	06	26	12	16	20	16	19	5E	7F	7F	01	77	77	77	11
0940	77	77	77	77	77	77	77	77	77	77	77	77	77	77	77	77
0950	13	00	17	00	0A	00	00	07	00	00	04	0D	09	2B	27	26
0960	06	0A	0C	12	0A	12	02	00	00	00	00	17	1F	1A	10	12
0970	00	00	92	10	A6	7D	A7	A5	98	9D	99	5D	A9	A6	99	61
0980	A5	94	7D	A5	D5	A6	92	04	A2	A9	D0	D3	0C	8E	D7	81
0990	9F	9F	A7	C1	D1	D1	D1	DA	AF	AD	A9	84	A6	A1	D0	9B
09A0	97	95	8D	9D	9C	9C	9C	95	A3	A1	9F	98	A6	9F	9D	9D
09B0	9B	96	7B	9D	9C	9D	8C	82	9E	77	94	90	88	8F	87	9E
09C0	8A	8F	96	81	8B	95	87	80	83	7F	7E	7C	77	74	6B	6F
09D0	73	76	75	7A	6B	83	7E	76	7A	7C	6F	74	6E	7B	72	7B
09E0	73	73	6C	6C	6B	64	64	70	6D	6E	70	6D	6E	6B	6A	00
09F0	00	00	00	00	00	00	00	77	77	6F	00	77	77	77	77	04

File name: DS01-007.hex