

INDIANA UNIVERSITY

TRANSPORTATION RESEARCH CENTER

School of Public and Environmental Affairs
222 West Second Street Suite A
Bloomington, Indiana 47403-1501
(812) 855-3908 Fax: (812) 855-3537

ON-SITE NOT IN TRAFFIC SURVEILLANCE BACK OVER INVESTIGATION

CASE NUMBER - IN08001
LOCATION - ARKANSAS
VEHICLE - 2007 HYUNDAI ELANTRA
CRASH DATE - November 2007

Submitted:

April 24, 2008
Revised: June 2, 2008



Contract Number: DTNH22-07-C-00044

Prepared for:

U.S. Department of Transportation
National Highway Traffic Safety Administration
National Center for Statistics and Analysis
Washington, D.C. 20590-0003

DISCLAIMERS

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

Technical Report Documentation Page

1. <i>Report No.</i> IN08001		2. <i>Government Accession No.</i>		3. <i>Recipient's Catalog No.</i>	
4. <i>Title and Subtitle</i> On-Site Not In Traffic Surveillance Back Over Investigation Vehicle - 2007 Hyundai Elantra Location - Arkansas			5. <i>Report Date:</i> April 24, 2008		
			6. <i>Performing Organization Code</i>		
7. <i>Author(s)</i> Special Crash Investigations Team #2			8. <i>Performing Organization Report No.</i>		
9. <i>Performing Organization Name and Address</i> Transportation Research Center Indiana University 222 West Second Street Bloomington, Indiana 47403-1501			10. <i>Work Unit No. (TRAIS)</i>		
			11. <i>Contract or Grant No.</i> DTNH22-07-C-00044		
12. <i>Sponsoring Agency Name and Address</i> U.S. Department of Transportation (NVS-411) National Highway Traffic Safety Administration National Center for Statistics and Analysis Washington, D.C. 20590-0003			13. <i>Type of Report and Period Covered</i> Technical Report Incident Date: November 2007		
			14. <i>Sponsoring Agency Code</i>		
15. <i>Supplementary Notes</i> On-site not in traffic surveillance back over investigation involving a 2007 Hyundai Elantra and a nonmotorist.					
16. <i>Abstract</i> This report covers an on-site not in traffic surveillance back over investigation involving a 2007 Hyundai Elantra and a nonmotorist, who was backed over in front of the driver's residence. The Hyundai was parked just off the edge of the roadway in the driver's front yard. The driver was in his residence with his family and decided to back the Hyundai into his driveway. The driver hurried out the front door so his 2-year-old son (i.e., the nonmotorist) would not follow him and ran to the Hyundai. However, unknown to the driver, the nonmotorist subsequently exited the front door and headed (i.e., the type of motion is unknown) toward the back of the Hyundai. Meanwhile, the driver had entered the Hyundai and was preparing to back up. He stated that he looked at both side view mirrors and the rearview mirror, saw nothing behind him, and began to back up while looking through the rearview mirror. The driver indicated that as he backed up, he felt a "bump" from under the vehicle, but thought he had backed over some tree roots on the roadside. He stopped the Hyundai and pulled forward. The driver stated he felt another bump and immediately stopped the vehicle, got out and discovered the nonmotorist on the ground near the Hyundai's right rear tire. The Hyundai's back bumper had impacted the nonmotorist, knocked him down, and the right rear tire ran over his head as the driver backed up and then pulled forward. The nonmotorist sustained skull fractures, a traumatic brain injury, a lacerated right ear and contusions to his head and face as a result of being run over by the Hyundai's right rear tire. He survived his injuries. There was insufficient information to determine the nonmotorist's location relative to the Hyundai when the driver looked through his side view mirrors and rearview mirror and began to back up.					
17. <i>Key Words</i> Back Over Child Injury			Motor Vehicle Traffic Incident Injury Severity		18. <i>Distribution Statement</i> General Public
19. <i>Security Classif. (of this report)</i> Unclassified		20. <i>Security Classif. (of this page)</i> Unclassified		21. <i>No. of Pages</i> 18	22. <i>Price</i>

TABLE OF CONTENTS

IN08001

Page No.

BACKGROUND 1

SUMMARY 1

CRASH CIRCUMSTANCES 1

CASE VEHICLE: 2007 HYUNDAI ELANTRA 3

 CASE VEHICLE DAMAGE 4

 CASE VEHICLE DRIVER 4

CASE VEHICLE VISIBILITY STUDY 4

NONMOTORIST 6

NONMOTORIST INJURIES 6

SCENE DIAGRAM 8

NOMINAL VISIBILITY DIAGRAM 9

ATTACHMENTS: NOT IN TRAFFIC SURVEILLANCE BACK OVER DATA FORMS

This incident was brought to the NHTSA's attention on or before November 16, 2007 by an on-line article from an Arkansas newspaper. This incident involved a 2007 Hyundai Elantra and a nonmotorist. The incident occurred in November, 2007, at 4:16 p.m., in Arkansas and was investigated by the applicable city police department. An incident report and Arkansas Motor Vehicle Crash Report were completed by the police agency, but neither were sent to any state agency. This contractor obtained a copy of the report from the police department. This incident is of special interest because the Hyundai's driver backed over a nonmotorist (2-year-old, male) who sustained moderate injuries. This contractor inspected the scene and Hyundai, and interviewed the Hyundai's driver on January 15, 2008. This report is based on the police incident report, Arkansas Motor Vehicle Crash Report, scene inspection, Hyundai inspection, and an interview with the Hyundai's driver.

SUMMARY

The Hyundai was parked just off the edge of the roadway in the driver's front yard. The driver was in his residence with his family and decided to back the Hyundai into his driveway. The driver hurried out the front door so his 2-year-old son (i.e., the nonmotorist) would not follow him and ran to the Hyundai. However, unknown to the driver, the nonmotorist subsequently exited the front door and headed (i.e., the type of motion is unknown) toward the back of the Hyundai. Meanwhile, the driver had entered the Hyundai and was preparing to back up. He stated that he looked at both side view mirrors and the rearview mirror, saw nothing behind him, and began to back up while looking through the rearview mirror. The driver indicated that as he backed up, he felt a "bump" from under the vehicle, but thought he had backed over some tree roots on the roadside. He stopped the Hyundai and pulled forward. The driver stated he felt another bump and immediately stopped the vehicle, got out and discovered the nonmotorist on the ground near the Hyundai's right rear tire. The Hyundai's back bumper had impacted the nonmotorist, knocked him down, and the right rear tire ran over his head as the driver backed up and then pulled forward. The nonmotorist sustained skull fractures, a traumatic brain injury, a lacerated right ear and contusions to his head and face as a result of being run over by the Hyundai's right rear tire. He survived his injuries. There was insufficient information to determine the nonmotorist's location relative to the Hyundai when the driver looked through his side view mirrors and rearview mirror and began to back up.

CRASH CIRCUMSTANCES

Crash Environment: The Hyundai Elantra was parked facing south (**Figure 1**) in the driver's front yard just off the west edge of a roadway that traversed north/south in front of the driver's residence. At the time of the incident, the light condition was daylight, the atmospheric condition



Figure 1: View south with Hyundai parked in same location as at time of incident; red reflector on tripod shows driver reported final rest location of nonmotorist

was clear, and the roadside was dry, level, dirt/gravel. The driveway the driver was intending to back into was dry concrete and had a negative grade of 10.3%. The site of the incident was located in a rural residential area. The Hyundai's driver met the SCI investigator at the scene of the incident and pointed out the parked and final rest positions of the Hyundai as well as the final rest position of the nonmotorist. See the Scene Diagram at the end of this report.



Figure 2: Overview of parked position of Hyundai, driveway and driver's residence

Pre-Crash: The Hyundai Elantra's driver was with his family inside their residence. His wife was in the shower and his three children [a 3-year-old female, a 2-year-old male (i.e., the nonmotorist) and an approximate 9-month-old (unknown sex)] were playing. The driver stated during the interview that he instructed the children to go into a bedroom and play while he went outside to back the Hyundai into the driveway of the residence (**Figure 2**). The police incident report indicated that the driver stated he "hurried outside so his son would not follow him". The driver closed the front door behind him as he exited the residence and ran from the door to the Hyundai. Unknown to the driver, the nonmotorist subsequently followed him outside. The driver approached the Hyundai, which was approximately 17 meters (56 feet) from the door of his residence, from the right. He ran across the back of the vehicle to the driver's side and entered the Hyundai through the left front door. Once inside the vehicle, the driver started the engine, then looked at both side view mirrors and the rearview mirror. He then began to back up while looking through the rearview mirror. The driver estimated the elapsed time between entering the Hyundai and beginning the backing maneuver was 10 seconds. At some point after the driver left the residence, the nonmotorist also exited the residence through the front door. The nonmotorist approached the Hyundai from the right. However, his specific path and motion as he approached the Hyundai is not known. The driver did not see the nonmotorist and thought he was still inside the residence. The driver's intention was to back the vehicle toward the driveway and then turn counterclockwise to back into the driveway. The incident occurred on the roadside, near the south edge of the driveway as the driver backed up.

Crash: The Hyundai's driver began backing up while looking through the rearview mirror. The driver wasn't sure if he simply let his foot off the brake to allow the Hyundai to idle backward or if he accelerated backward. As he backed up, he felt a "bump" from under the vehicle, but thought he had backed over some tree roots on the roadside. The driver estimated that he had backed up between 2 and 5 seconds before the "bump" occurred. He stopped the Hyundai, shifted the transmission into "Drive" and then pulled forward. He felt another bump and immediately stopped the vehicle. Based on the police incident report, the right portion of the Hyundai's back bumper (**Figure 3** below) initially impacted the nonmotorist. The Hyundai's right rear tire then ran over the nonmotorist's head as the driver backed up, and again when he pulled forward. Based on the driver's indicated position of the nonmotorist at final rest and the parked location of the Hyundai, the distance that the Hyundai traveled backward from its parked position to the initial

impact was estimated to be 1.7 meters (6 feet). The Hyundai then traveled backward from impact 1.7 meters (6 feet) where the driver indicated he initially stopped. The driver then pulled forward 2.3 meters (7 feet) to the location where the driver stopped the vehicle. The total travel distance from the initial impact to final rest of 4 meters (13 feet). The driver stated he thought he was traveling approximately 5 km.p.h. (~3 m.p.h.) when the incident occurred. There was insufficient information to support an independent speed analysis. In addition, there was insufficient information to determine the nonmotorist's specific path and motion as he approached the Hyundai and his location relative to the Hyundai when the driver looked through his rearview and side view mirrors and began to back up.

Post-Crash: The Hyundai's driver got out of the vehicle and saw the nonmotorist laying on his left side with his head toward the street (**Figure 4**) bleeding heavily from his head. The driver picked up the nonmotorist and ran into the house yelling for help from his wife. The driver's wife took the nonmotorist and ran outside and began yelling for a neighbor to call 911. The driver ran to a second neighbor's house and told them to call 911. The nonmotorist was transported by ambulance to a local hospital and subsequently airlifted to an urban children's medical center. The nonmotorist survived and was hospitalized for five days and discharged. He sustained skull fractures, a traumatic brain injury, a lacerated right ear and contusions to his head and face.

CASE VEHICLE

The 2007 Hyundai Elantra (**Figures 5 and 6** below) was a front wheel drive, four-door sedan (VIN: KMHDU46D57U-----) equipped with a 2.0L, I-4 engine and automatic transmission. Its back bumper was covered with a plastic bumper fascia with energy absorbing material between the bumper fascia and bumper bar. None of the Hyundai's glazing was tinted. The Hyundai was not equipped with any after market equipment and was not equipped with a back up/parking aid. The Hyundai's specified wheelbase was 265 centimeters (104.3 inches), the specified rear overhang was 99 centimeters (38.9 inches), and the specified overall length was 451 centimeters (177.4 inches). The measured distance from the ground to the bottom of the back bumper fascia



Figure 3: Overview of back of Hyundai, scratches on bumper are not related to this incident, vertical scale in 10th of meter



Figure 4: Overview of scene of incident from front yard of driver's residence; arrows indicate from left to right: 1 driver reported back of Hyundai at initial stop; 2 driver reported final rest position of nonmotorist; 3 approximate location of nonmotorist at impact with bumper; 4 driver reported position of back of Hyundai at final rest; Hyundai in driver reported initial parked position

was 27 centimeters (10.6 inches). The measured distance from the ground to the rear axle was 13 centimeters (33 inches). The measured distance from the ground to the top of the trunk was 105 centimeters (41.3 inches). The measured distance from the ground to the beltline was 96 centimeters (37.8 inches).

CASE VEHICLE DAMAGE

Inspection of the Hyundai Elantra revealed no damage or evidence of contact with the nonmotorist. Some heavy scratches to the back bumper fascia were located to the right of the vehicle's centerline. The driver indicated that the damage was from a previous incident. Based on the police incident report, which indicated the area on the back bumper where the initial impact occurred, the reported contact to the right rear tire, and the Collision Deformation Classification (CDC) guidelines for pedestrian impacts, the CDCs were determined to be: **06-BRLN-1 (180 degrees)** and **12-FRWN-9 (0 degrees)**.

CASE VEHICLE DRIVER

The Hyundai's driver was a 22-year-old, White (non-Hispanic) male. He was 175 centimeters (69 inches) tall and weighed 104 kilograms (230 pounds). He drove the Hyundai every day and had owned the vehicle for eight or nine months. He did not have a vision deficiency and was not wearing sunglasses at the time of the incident. The police incident report indicated that the driver displayed no signs of alcohol or drug usage; however, the driver was given a blood test. Numerous attempts were made to obtain the test results, but they were never forwarded to this contractor.

CASE VEHICLE VISIBILITY STUDY

A visibility study was conducted during the inspection of the Hyundai Elantra in order to determine the nominal blind zone behind the vehicle as well as the nominal blind zone of both side view mirrors and the rearview mirror. The standard 71 centimeters (28 inches) high target was used for the observations. The Hyundai driver assisted the SCI investigator in making the visibility observations and the Hyundai was placed in the same parked location as at the time of the incident. The driver's eye height was measured as he sat in the driver seat with the seat adjusted to the approximate middle track position, which was his normal seat track position. The driver's eye height was measured as 116 centimeters (45.7 inches) above the ground. Please refer



Figure 5: Front right view of subject Hyundai Elantra



Figure 6: Back right view of subject Hyundai Elantra, scratches on back bumper are not related to this incident

to the Nominal Visibility Diagram at the end of this report when reading the following description.

The initial set of observations was made with the driver looking over his right shoulder out of the backlight (Figure 7). The target was moved rearward from the back bumper along the Hyundai's approximate centerline until it came into the driver's view (Figure 7). The target had to be moved rearward from the back bumper 7.1 meters (23.3 feet) before the top of target came into the driver's view. The target was then moved to the right 0.8 meter (2.6 feet) where it became obstructed by the Center High Mounted Stop Lamp (CHMSL). The target became visible again when moved 1.3 meters (4.3 feet) further to the right. When the target was moved 1.9 meters (6.2 feet) further to the right, it dropped out of the driver's sight. This is because the location of the target placed it on the negatively sloped (-10.3 %) driveway. The target was moved further to the right and became visible to the driver through the right rearmost window when moved right an additional 3.6 meters (11.8 feet). The target was then placed back to its initial position at the approximate centerline. When moved 0.3 meter (0.7 foot) to the left of the approximate centerline, it became obstructed by the back left head restraint. From this point, the target was not visible to the driver because it was not normal for the driver to turn his head any further to the right.



Figure 7: View out of Hyundai's backlight from driver's seat; arrow shows target in location where driver could first see it

The Hyundai's driver was then asked to view behind the vehicle through the rearview mirror (Figure 8), which he indicated he had not adjusted prior to this contractor's on-site investigation. It was in the same position as at the time of the incident. The target was moved rearward from the back bumper as the driver viewed through the rearview mirror. The target did not become visible to the driver until it was moved rearward 7.3 meters (23.9 feet). The target became obstructed by the (CHMSL) when moved to the right 0.2 meter (0.7 foot) and became visible again when moved right an additional 0.5 meter (1.6 feet). When moved 0.6



Figure 8: Close view through Hyundai's rearview mirror from driver's seat

meter (2 feet) further to the right, the target became obstructed by the back right head restraint. The target did not become visible again when moved further to the right because it went out of the rearview mirror's field of view. The target was returned to the initial location at the approximate centerline and when moved left, was immediately obstructed by the back left head restraint and was not visible again when moved further to the left.

The target was then placed at the back left bumper corner as the driver viewed through the left side view mirror (Figure 9). The driver did not adjust his side view mirrors often and could not recall the last time he had adjusted the side view mirrors. When the target was placed at the back left bumper corner, it was necessary to move the target 0.9 meter (3 feet) to the left before it went out of the mirror’s view. The target was repositioned at the back left bumper corner and moved forward, toward the left side view mirror. The target went out of the mirror’s field of view when moved forward 0.7 meter (2.3 feet) from the bumper corner. The target was then positioned at the back right bumper corner and the same process was repeated for the right side view mirror (Figure 10). When moved laterally to the right 0.9 meter (3 feet), the target went out of the mirror’s field of view. The target was then placed back at the back right bumper corner, and moved 0.9 meter (3 feet) forward where it went out of the mirror’s field of view and the driver could no longer see it.



Figure 9: Close view through Hyundai’s left side view mirror; arrow shows target at location it began to go out of driver’s view as it was moved forward from back left bumper corner



Figure 10: Close view through Hyundai’s right side view mirror from driver’s seat, arrow shows target at location it began to go out of driver’s view as it was moved forward from the back right bumper corner

NONMOTORIST

The nonmotorist was a 2-year-old, White (non-Hispanic) male. He was 97 centimeters (38 inches) tall and weighed 13 kilograms (29 pounds). According to the driver, he was wearing camouflage shorts, a yellow t-shirt, and blue “cros” shoes.

NONMOTORIST INJURIES


The nonmotorist sustained moderate injuries. The table below shows the nonmotorist’s injuries and injury mechanisms.


Injury Number	Injury Description (including Aspect)	NASS Injury Code & AIS 90	Injury Source (Mechanism)	Source Confidence	Source of Injury Data
1	Fracture right skull behind ear;	moderate	Tire, right rear	Certain	Interviewee (driver)
2	Fracture left skull behind ear	150400.2,1 150400.2,2			

Case Vehicle Nonmotorist Injuries (Continued)

IN08001

Injury Number	Injury Description (including Aspect)	NASS Injury Code & AIS 90	Injury Source (Mechanism)	Source Confidence	Source of Injury Data
3	Traumatic brain injury, not further specified	unknown 115099.7,0	Tire, right rear	Certain	Police Accident Report
4	Laceration, severe, to right ear, not further specified	minor 290600.1,1	Tire, right rear	Certain	Interviewee (driver)
5	Contusion {bruises}, multiple, head, not further specified	minor 190402.1,9	Tire, right rear	Certain	Interviewee (driver)
6	Contusion {bruise}, multiple, face, not further specified	minor 290402.1,9	Tire, right rear	Certain	Interviewee (driver)







1. Case Number

IDENTIFICATION

2. Date of Crash ____ / ____ / ____

3. Time of Crash _____

Code reported military time of crash.

NOTE: Midnight = 2400
Unknown = 9999

AMBIENT CONDITIONS

4. Light Conditions

- Daylight
- Dark
- Dark but lighted
- Dawn
- Dusk
- Unknown

5. Atmospheric Conditions
(Select all that apply)

- Clear-No adverse conditions
- Cloudy
- Rain
- Snow
- Fog, Smog, Smoke
- Sleet, Hail (freezing rain or drizzle)
- Blowing Snow
- Severe Crosswinds
- Blowing Sand, Soil, Dirt
- Other (specify):
- Unknown

6. Temperature

- Below 0 degrees Celsius (Below 32 F)
- 1-10 degrees Celsius (33-50 F)
- >10-24 degrees Celsius (51-75 F)
- Over 24 degrees Celsius (Over 75 F)
- Unknown

SCENE INFORMATION

7. Type of area in which crash occurred
(Select all that apply)

- Single family residential
- Row houses/townhouses
- Multi family housing
- Commercial
- Industrial
- Rural
- Unknown

8. Driver exterior sightline obstructions
(Select all that apply)

- None
- Other vehicles
- Building
- Trees
- Shrubby
- Other (specify) _____
- Utility poles
- Signs
- Glare
- Unknown
- No driver present

9. Crash location

- Driveway
- Parking Lot
- Sidewalk
- Alley
- Intersection of driveway and sidewalk
- Road / street
- Roadside / shoulder
- Other (specify) _____
- Unknown

10. Non motorist sightline obstructions
(Select all that apply)

- None
- Other vehicles
- Building
- Trees
- Shrubby
- Utility poles
- Signs
- Glare
- Other (specify) _____
- Unknown

11. Grade at parked position _____ +/- %

12. Estimated distance from parked position to impact

_____ m

13. Estimated speed at impact _____ +/- kmph

14. Grade at impact _____ +/- %

15. Estimated distance from impact to vehicle final rest

_____ m

Unknown = 999 Reference Items 11,12, 13, 14, 15



1. Case Number _____

VEHICLE IDENTIFICATION

2. VIN _____

3. Model Year _____

4. Vehicle Make (specify): _____

5. Vehicle Model (specify): _____

GLAZING

Location	Presence (check)	Status (select)	Clarity (select)	Tint (check)	Glazing Obstructions (specify if present)
Windshield		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
LF		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
RF		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
2 nd Left		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
2 nd Right		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
3 rd Left		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
3 rd Right		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
Backlight		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
Left Backlight		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
Right Backlight		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
Roof		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		
Other (specify)		Fixed / Closed / Open / Partially Open / Unknown	Clear / Hazy / Very Dirty / Unknown		

TIRE DATA

6. Vehicle Manufacturer Recommended Tire Size _____

7. LF Tire Size _____

9. RF Tire Size _____

8. LR Tire Size _____

10. RR Tire Size _____

Seats / Head Restraint Data

Seat Position	Seat Type (Select from below)	Head Restraint (Check if available)	Head Restraint Adjustment (select)	NOTES:
Front Left			Full Down / Mid / Full Up	
Front Middle			Full Down / Mid / Full Up	
Front Right			Full Down / Mid / Full Up	
2 nd Left			Full Down / Mid / Full Up	
2 nd Middle			Full Down / Mid / Full Up	
2 nd Right			Full Down / Mid / Full Up	
3 rd Left			Full Down / Mid / Full Up	
3 rd Middle			Full Down / Mid / Full Up	
3 rd Right			Full Down / Mid / Full Up	

Seat Type codes:

- | | |
|---|--------------------------------------|
| 0 = No seat or seat folded down | 8 = Pedestal (i.e. column supported) |
| 1 = Bucket | 9 = Box mounted (i.e. van type) |
| 2 = Bucket w/ folding back | 10= Other seat type (specify) |
| 3 = Bench | 99= Unknown seat type |
| 4 = Bench with folding back cushions | |
| 5 = Bench w/ folding back | |
| 6 = Split bench w/ separate back cushions | |
| 7 = Split bench w/ separate folding back | |

VEHICLE MEASUREMENTS

Clearance Heights	Measurements (all from ground, and in centimeters)	NOTES
Beltline		
Top of trunk/tailgate		
Bottom of bumper		
Trailer hitch (if applicable)		
Undercarriage		
Sway bar		
Axle		
Differential		
Other (specify):		
Sensor Height (if equipped)		
Camera Height (if equipped)		



1. Case Number

PARKING AID PRESENCE

2. Type of backing/parking aid present

- OEM camera
- OEM ultrasonic/radar sensor
- OEM combination camera-ultrasonic/radar sensor
- OEM Fresnel lens
- OEM interior mirrors
- Aftermarket camera
- Aftermarket ultrasonic/radar sensor
- Aftermarket combination camera-ultrasonic radar sensor
- Aftermarket Fresnel lens
- Aftermarket interior mirrors
- Other (specify): _____

CAMERA INFORMATION

Specify field of view measurements on diagram

3. System make/model

4. Video monitor type

- None present
- LCD (color)
- CRT (black & white)
- Unknown

5. Video display size _____ cm
(Diagonal)

6. Camera location

- None present
- Bumper
- License plate
- Tailgate/Hatch/Trunk
- Other (specify): _____

7. Video image quality under scene lighting conditions

- None present
- Good
- Average
- Poor (specify): _____
- Unknown

8. Was the camera functioning properly

- None present
- Yes
- No, poor image quality due to glare
- No, poor image quality due to atmospheric conditions
- No, camera turned off
- No, camera inoperable
- Unknown

ULTRASONIC/RADAR SENSOR

Specify object detection range on diagram

9. System make/model

10. Auditory warning illumination

- No sensor present
- Yes
- No
- Unknown

11. Number of sensors _____

12. Sensor locations
(Select all that apply)

- No sensor present
- Left bumper
- Center bumper
- Right bumper
- License plate area
- Tailgate/Hatch/Trunk

13. Was warning system functioning properly

- No sensor present
- Yes, system alerted driver
- No, system did not alert driver
- No, system turned off
- No, system inoperable
- Unknown

14. Did driver react to warning

- No sensor present
- Yes
- No
- Unknown

15. Did driver report common false warnings

- No sensor present
- Yes
- No
- Unknown



DRIVER FORM

1. Case Number

DRIVER PROFILE

2. Driver's Age _____
99 = Unknown

3. Driver's Sex Male
 Female
 Unknown

4. Driver's Height _____ cm
999 = Unknown

5. Driver's Weight _____ kg
999 = Unknown

6. Driver eyewear worn
(Select all that apply)
 None
 Eyeglasses
 Sunglasses
 Contacts
 Unknown

7. Driver vision deficiency condition
(Select all that apply)
 None
 Near sighted
 Far sighted
 Astigmatism
 Other (specify): _____
 Unknown

8. Non motorist's relationship to driver
 No relationship
 Child
 Grandchild
 Sibling
 Neighbor
 Friend
 Other (specify): _____
 Unknown

DRIVER ACTIONS

9. Driver approach to vehicle for entry
From left front
 From left
 From left rear
 From right rear
 From right front
 Circled vehicle
 Return trip (backing into driveway/lot)
 Other (specify): _____
 N/A
 Unknown

10. Driver entry interruption
(Select all that apply)
 Direct trip from building to vehicle
 Loaded items into vehicle
 Spoke with family
 Spoke with neighbors
 Spoke with contacted nonmotorist
 Return trip (backing into driveway/lot)
 Other (specify): _____
 N/A
Unknown

11. Purpose of backing
 Leaving parking space in parking lot
 Backing onto roadway from driveway
 Entering parking space in parking lot
 Backing into driveway from roadway
 Other (specify): _____
 N/A
Unknown

12. Where was driver going
Description:

13. Driver in a hurry
 Yes N/A
 No Unknown
 Unknown

14. How did driver check behind (rear area of vehicle)
after vehicle entry
(Select all that apply)
 Did not look
 Checked mirrors
 Turned right and looked back
 Turned left and looked back
 Viewed Camera
 Listened for auditory/visual warning from system
 Other (specify): _____
N/A Unknown

15. Estimated time between vehicle entry and start
of backing
 0-10 Seconds Over 60 Seconds
 11-30 Seconds N/A
 31-60 Seconds Unknown

16. What direction was the driver looking during backing maneuver
(Select all that apply)
- Straight ahead
 - Right
 - Left
 - Rearward
 - At object inside the car
 - At mirrors
 - Other (specify): _____
 - N/A
 - Unknown
17. Was the driver distracted during back up maneuver
(Select all that apply)
- No non-driving activities
 - External**
 - Looking at other vehicles
 - Looking at other non motorist
 - Looking at intended turn destination
 - External focus, not specified
 - Other external focus (specify): _____
 - Internal**
 - Looking at other occupant
 - Talking to passenger
 - Dialing phone
 - Talking on phone
 - Listening to radio/cd/portable playback device
 - Adjusting radio/cd player
 - Adjusting climate controls
 - Using a device/controls integral to vehicle (specify): _____
 - Reading/adjusting navigation system
 - Eating or drinking
 - Smoking related
 - Retrieving fallen object (specify): _____
 - Internal focus, not specified
 - Focused on other internal object (specify): _____
 - N/A
 - Unknown
18. Driver avoidance actions prior to impact
(Select all that apply)
- None
 - Braking
 - Steering left
 - Steering right
 - Accelerating
 - Other (specify): _____
 - N/A
 - Unknown

19. Did driver see struck non motorist prior to impact
(Select all that apply)
- No, never saw non motorist
 - Saw non motorist prior to entering vehicle
 - Saw non motorist after entering vehicle
 - Other (specify): _____
 - N/A
 - Unknown
20. Est time between start of backing and impact
- <2 or = 1 second
 - 2-5 seconds
 - 6-10 seconds
 - > 10 seconds
 - N/A
 - Unknown
21. Driver interior sightline obstructions
(Select all that apply)
- Pillar
 - Headrest
 - Cargo
 - Other occupant
 - Other (specify) _____
 - Unknown
 - None
22. Recent experience driving this vehicle
- More than 10 times the last three months
 - 6-10 times the last three months
 - 2-5 times the last three months
 - Less than 2 times the last three months
 - First time driving this vehicle
 - N/A
 - Unknown
23. Frequency of driving in this parking lot/driveway
- Daily
 - Weekly
 - Several times a month
 - Monthly
 - Rarely
 - First time in lot/driveway
 - N/A
 - Unknown
24. Driver Impairment
(Select all that apply)
- No drugs or alcohol present
 - Alcohol present (specify BAC): _____
 - Drugs present (specify): _____
 - Unknown
25. Source of alcohol/drug results
- Police reported
 - Medical record
 - Other (specify) _____
 - Not Tested
 - Unknown if tested



Non Motorist Form

1. Case Number

NON-MOTORIST PROFILE

2. Non-motorist's Age _____ Months
_____ Years
99 = Unknown

3. Non-motorist's Sex
 Male
 Female
 Unknown

4. Non-motorist's Height _____ cm
999 = Unknown

5. Non-motorist's Weight _____ kg
999 = Unknown

6. Medical outcome
 Not injured
 ER only
 Hospitalized 1-4 days
 Hospitalized 5 days or more
 Treatment later
 Fatal
 Unknown

7. Source of most severe injury
 Bumper
 Tire
 Undercarriage
 Other Specify: _____
 Ground
 N/A
 Unknown

8. Non-motorist impairment
(Select all that apply)
 No drugs or alcohol present
 Positive for alcohol (specify BAC): _____
 Positive for drugs (specify): _____
 Unknown

9. Source of alcohol/drug results
 Police reported
 Medical Report
 Other (specify) _____
 Not Tested
 Unknown if tested

NON-MOTORIST ACTIONS

10. Non-motorist attitude
 Standing
 Bending at waist
 Sitting
 Crouching
 Kneeling
 On skates/skateboard
 On bike/scooter
 Other (specify) _____
 Unknown

11. Non-motorist motion
 Not moving
 Walking slowly
 Walking rapidly
 Running or jogging
 Skipping/Hopping/Jumping
 Falling/Stumbling/Rising
 On skates/skateboard
 On bike/scooter
 Other (specify): _____
 Unknown

12. Non-motorist approach relative to rear of vehicle
 Stationary
 From left
 From right
 From behind
 Other (specify): _____
 Unknown

13. Non-motorist first avoidance action
 No avoidance actions
 Stopped
 Accelerated pace
 Ran away (along vehicle path)
 Jumped
 Turned away from vehicle
 Turned toward vehicle and braced
 Dove or fell away from vehicle
 Other (specify): _____
 Unknown

14. Non-motorist primary focus of attention
 Striking vehicle
 Play object
 Person
 Surrounding traffic
 Animal
 Handheld electronic (phone, MP3 player, etc.)
 Other Object (specify) _____
 Unknown

15. Were any other Non-motorists present?
(Select all that apply)
 Alone
 One adult present
 One other child present
 Multiple adults present
 Multiple children present
 Unknown

NON MOTORIST CLOTHING

NOTES:

- Specify Color, Fabric and Texture/Weight for outermost layer only
- Indicate "NONE" if applicable
- Available codes:

	<u>Colors</u>		<u>Fabrics</u>		<u>Textures</u>		<u>Weights</u>
Black	Charcoal gray		Natural		Soft		Heavy
Lt gray/silver	Brown		Synthetic		Slick		Medium
Gold/tan	Purple		Blend		Coarse		Light
Dark blue	Light blue						
Dark green	Light green						
Maroon	Red						
Orange	Yellow						
White	Other (specify)						

	Clothing	Color	Fabric	Texture	Weight
H E A D W E A R	Hat				
	Helmet				
	Hood				
	Other (specify): _____				
U P P E R B O D Y	Short Sleeve				
	Long Sleeve				
	Light Jacket				
	Heavy Jacket				
	Other (Specify): _____				
L O W E R B O D Y	Shorts				
	Pants				
	Shoes				
	Other (specify): _____				