

**RECEIVED**

By Recall Management Division at 3:19 pm, May 17, 2011



**PORSCHE**

**VIA UPS**

May 6, 2011

Ms. Kathleen Demeter  
Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
400 Seventh Street, S.W. (NVS-200)  
Washington, D.C. 20590

Porsche Cars North America, Inc.  
980 Hammond Drive  
Suite 1000  
Atlanta, Georgia 30328  
(770) 290-3500 Fax: (770) 290-3700

RE: Defect Notification Reports for Model Year 2010-11 Porsche 911 Turbo/GT2/GT3 models and Dealer Installed Tequipment Central Wheel Lock/Central Wheel Bolts

Dear Ms. Demeter:

Porsche Cars North America, Inc. (PCNA) on behalf of Dr. Ing. h.c.F. Porsche AG (Porsche AG) hereby informs you of Porsche's intention to conduct safety related recall and remedy campaigns involving 2010 and 2011 Model Year Porsche 911 Turbo, 911 Turbo S, 911 GT3, 911 GT3 RS and 911 GT2 RS vehicles and dealer installed Tequipment Central Wheel Lock/Central Wheel Bolts.

On behalf of Porsche AG, Porsche Cars North America, Inc. has enclosed two defect reports pursuant to the provisions of Part 573 of Title 49 of the Code of Federal Regulations, one for the subject vehicles and one for the dealer installed accessory (Tequipment).

Should you have any questions or require further information, please do not hesitate to contact me at (770) 290-3627.

Sincerely,

A handwritten signature in dark ink, appearing to read "Walter J. Lewis".

Walter J. Lewis, Manager  
Regulatory Affairs

Enclosures

cc: George Person, NHTSA - ODI via facsimile

# PORSCHE

## PART 573 Defect and Noncompliance Report

On April 29, 2011, Porsche decided that a defect which relates to motor vehicle safety exists in the motor vehicles listed below and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Reports.

Date this report was prepared: **May 6, 2011**

Manufacturer's identification code: **AB01**

1. Identify the full corporate name of the fabricating manufacturer of the vehicle being recalled. If the recalled vehicle is imported, provide the name and mailing address of the designated agent as prescribed by 49 U.S.C. §30164.

**Manufacturer**

**Dr. Ing. h.c.F. Porsche AG  
70435 Stuttgart  
Germany**

**Agent**

**General Counsel and Secretary  
Porsche Cars North America, Inc.  
980 Hammond Drive  
Suite 1000  
Atlanta, GA 30328**

Corporate official, whom the agency should contact with respect to this recall:

**Walter J. Lewis  
Regulatory Affairs Manager  
Tel. No: (770) 290-3627  
Fax No.: (770) 290-5508**

Signed



---

# PORSCHE

## PART 573 Defect and Noncompliance Report

### I. Identify the Vehicle Models involved in the Recall

#### 2. Vehicles Involved in the Recall:

Make: **Porsche**

Model Year: **2010 - 2011**

Models: **911 Turbo  
911 Turbo S  
911 GT3  
911 GT3 RS  
911 GT2 RS**

Production Dates: **May 18, 2009 to September 17, 2010**

VIN Ranges: **WPOAC2A90AS783072 to WPOCD2A9XBS773477**

Vehicle Type: **Passenger car.**

Bodystyle: **2-door coupe.**

Descriptive information which characterizes/distinguishes the recalled vehicles from those models not included in the recall:

**Not every Porsche 911 Turbo vehicle is equipped with the optional center locking wheel and hub assemblies; this feature was an option on that model. The feature was standard equipment on, and was installed on 100% of every other model included in this recall. Whether or not a particular 911 Turbo vehicle was equipped with the optional center locking wheel and hub assemblies is easily discerned by looking at the exterior of the vehicle, and by reviewing the list of options installed on the vehicle.**



## **PART 573 Defect and Noncompliance Report**

Identify the approximate percentage of the production of all the recalled models manufactured by your company between the inclusive dates of manufacture provided above, that the recalled model population represents.

**100% of all included vehicles except for the 911 Turbo; the installation rate of the subject option on that model is to be determined.**

### **II. Identify the Recall Population**

3. Furnish the total number of vehicles recalled potentially containing the defect or noncompliance.

Total Number Potentially Affected by the Recall: **1,702**

4. Approximate percentage of the total number of vehicles above estimated to actually contain the defect or noncompliance:

**100%.**

Identify and describe how the recall population was determined:

**To be determined.**

# PORSCHE

## PART 573 Defect and Noncompliance Report

### III. Describe the Defect or Noncompliance

#### 5. Describe the defect or noncompliance.

**Porsche is aware that some customers of the affected vehicles occasionally operate them on a racetrack or under similar conditions. From Porsche's own racing experience with vehicles using the same central wheel lock components, Porsche has developed new components as well as additional instructions for the use of such components when the affected vehicles are operated under racing conditions.**

Describe the cause of the defect or noncompliance condition.

**See above.**

Describe the consequence of the defect or noncompliance condition.

**Should be affected vehicles be operated under racing conditions, there is a small possibility that the wheel retention system may fail, resulting in a crash.**

Identify any warning, which can (a) precede or (b) occur.

**None.**

## **PART 573 Defect and Noncompliance Report**

Identify the supplier by corporate name and address, and the name and title of the chief executive officer or knowledgeable representative of the supplier:

**To be determined.**

### IV. Provide the Chronology in Determining the Defect/Noncompliance

6. With respect to a defect, furnish a chronological summary (including dates) of all the principle events that were the basis for the determination of the defect. The summary should include, but not be limited to, the number of reports, accidents, injuries, fatalities, and warranty claims.

**To be determined.**

7. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.

**Not applicable.**

### V. Identify the Remedy

8. Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.

**The affected vehicles will be recalled to the workshop and the central bolts will be replaced and fitted in accordance with the new greasing specification. A new owners manual supplement will also be added to the vehicles documentation portfolio. In addition, any mating components will be inspected and replaced as necessary.**

# PORSCHE

## **PART 573 Defect and Noncompliance Report**

Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

**The originally installed bolts bear an inscription of the previously required tightening torque specification. The replacement bolts no longer bear this inscription.**

Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

**To be determined.**

### VI. Identify the Recall Schedule

Furnish a schedule or agenda (with specific dates) for notification to dealers and purchasers.

**To be determined.**

### VII. Furnish Recall Communications

9. Furnish a final copy of all notices, bulletins, and other communications that relate directly to the defect or noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications (including both original and follow-up) concerning this recall from the time your company determines the defect or noncompliance condition on, not just the initial notification.

**Attached is a draft copy of the Technical Information Bulletin. The remaining documents will be forwarded as soon as available.**