



VIA UPS

June 9, 2011

Ms. Kathleen Demeter Associate Administrator for Enforcement National Highway Traffic Safety Administration 400 Seventh Street, S.W. (NVS-200) Washington, D.C. 20590 Porsche Cars North America, Inc. 980 Hammond Drive Suite 1000 Atlanta, Georgia 30328 (770) 290-3500 Fax: (770) 290-3700

RE:

<u>Updated Defect Notification Reports for Model Year 2010-11 Porsche 911 Turbo/GT2/GT3 models and Dealer Installed Tequipment Accessory Central Wheel Lock/Central Wheel Bolts</u>

Dear Ms. Demeter:

Enclosed please find two updated reports containing missing information not included in the original reports submitted on May 6, 2011, pursuant to the provisions of Part 573 of Title 49 of the Code of Federal Regulations, one for the subject vehicles and one for the dealer installed accessory (Tequipment).

Should you have any questions or require further information, please do not hesitate to contact me at (770) 290-3627.

Sincerely

Walter J. Lewis, Manager

Regulatory Affairs

Enclosures

cc: George Person, NHTSA - ODI via facsimile



PART 573 Defect and Noncompliance Report (Update)

On April 29, 2011, Porsche decided that a defect which relates to motor vehicle safety exists in the motor vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 <u>Defect and Noncompliance Reports.</u>

Date this report was prepared:

June 9, 2011

Manufacturer's identification code:

AB01

1. Identify the full corporate name of the fabricating manufacturer of the vehicle being recalled. If the recalled vehicle is imported, provide the name and mailing address of the designated agent as prescribed by 49 U.S.C. §30164.

Manufacturer
Dr. Ing. h.c.F. Porsche AG
70435 Stuttgart
Germany

Agent
General Counsel and Secretary
Porsche Cars North America, Inc.
980 Hammond Drive
Suite 1000
Atlanta, GA 30328

Corporate official, whom the agency should contact with respect to this recall:

Walter J. Lewis

Regulatory Affairs Manager Tel. No: (770) 290-3627

Fax No.: (770) 290-5508

M/h:

Signed

PART 573 Defect and Noncompliance Report (Update)

- I._Identify the Vehicle Models involved in the Recall
- 2. Vehicles Involved in the Recall:

Make:

Porsche

Model Year:

2010 - 2011

Models:

911 Turbo 911 Turbo S 911 GT3 911 GT3 RS

911 GT2 RS

Production Dates:

May 18, 2009 to September 17, 2010

VIN Ranges:

WPOAC2A90AS783072 to WPOCD2A9XBS773477

Vehicle Type:

Passenger car

Bodystyle:

2-door coupe

Descriptive information which characterizes/distinguishes the recalled vehicles from those models not included in the recall:

Not every Porsche 911 Turbo vehicle is equipped with the optional center locking wheel and hub assemblies; this feature was an option on that model. The feature was standard equipment on, and was installed on 100% of, every other model included in this recall. Whether or not a particular 911 Turbo vehicle was equipped with the optional center locking wheel and hub assemblies is easily discerned by looking at the exterior of the vehicle, and by reviewing the list of options installed on the vehicle.

PART 573 Defect and Noncompliance Report (Update)

Identify the approximate percentage of the production of all the recalled models manufactured by your company between the inclusive dates of manufacture provided above, that the recalled model population represents.

100% of all included vehicles except for the 911 Turbo; the installation rate of the subject option on that model is to be determined.

- II. Identify the Recall Population
- 3. Furnish the total number of vehicles recalled potentially containing the defect or noncompliance.

Total Number Potentially Affected by the Recall:

1,702

4. Approximate percentage of the total number of vehicles above estimated to actually contain the defect or noncompliance:

100%

Identify and describe how the recall population was determined:

All vehicles equipped with center wheel lock and hub assemblies as standard of optional equipment bearing the torque specification inscription "500 Nm" on the center bolt. The affected components were manufactured from the start of production up to September 16, 2010.

June 9, 2011 Page 3 of 8

PART 573 Defect and Noncompliance Report (Update)

Ш	Describe	the	Defect	or None	compliance
Hŧ.	DESCRIPE	HIC	レビュー	UI INUIR	JUHUNGHUC

5. Describe the defect or noncompliance.

Porsche is aware that some customers of the affected vehicles occasionally operate them on a racetrack or under similar conditions. From Porsche's own racing experience with vehicles using the same central wheel lock components, Porsche has developed new components as well as additional instructions for the use of such components when the affected vehicles are operated under racing conditions.

Describe the cause of the defect or noncompliance condition.

See above.

Describe the consequence of the defect or noncompliance condition.

Should the affected vehicles be operated under racing conditions there is a small possibility that the wheel retention system may fail resulting in a crash.

Identify any warning, which can (a) precede or (b) occur.

None.

June 9, 2011 Page 4 of 8

PART 573 Defect and Noncompliance Report (Update)

Identify the supplier by corporate name and address, and the name and title of the chief executive officer or knowledgeable representative of the supplier:

The supplier group is:

Hirschvogel Holding GmbH Mühlstr. 6 86920 Denklingen GERMANY

The manufacturer of the center wheel lock is:

Hirschvogel Komponenten GmbH Rossau Str. 3 86956 Schongau GERMANY

Technical Director: Mr. Albert Kees

Telephone Number 011 49-886-191-0101

E-mail: albert.kees@hirschvogel.de

Please note: The torque specifications for fastening the wheel to the vehicle was determined by Porsche AG and not the supplier.

IV. Provide the Chronology in Determining the Defect/Noncompliance

6. With respect to a defect, furnish a chronological summary (including dates) of all the principle events that were the basis for the determination of the defect. The summary should include, but not be limited to, the number of reports, accidents, injuries, fatalities, and warranty claims.

August 2010

A German Porsche Dealer which sponsors racing teams in competitive events on European racetracks informed Porsche AG of a broken center locking wheel and hub assembly on a 911 Carrera GT3 sports car operated under semi professional racing conditions.

June 9, 2011 Page 5 of 8

PART 573 Defect and Noncompliance Report (Update)

A subsequent internal check of field reports did not indicate any such incidents with vehicles on public roads.

<u>August 2010 - November 2010</u>

Investigations from Porsche AG staff took place on racetracks in conjunction with the last European races of the season. In total, three cases with broken center wheel hubs were discovered on the racetrack. In two cases there were accidents on the racetrack after the hub failed. No injuries or fatalities resulted from these accidents.

As an immediate measure a Technical Information Bulletin "Central wheel lock: Additional instructions for driving on race circuits (73/10)" was released via Porsche subsidiaries to the Porsche dealers and racing teams. The technical information provided instructions for additional maintenance and service of the center locking wheel and hub assembly as well as an increase of the tightening torque specification to 600 Nm (from 500 Nm as imprinted on the bolt) for fixing the center wheel bolt.

Also, the internal check of field reports was intensified in order to determine whether the additional instructions need to be extended to include public road use. The field reports did not provide any cases of broken center locking wheel and hub assemblies. Nevertheless, the Product Safety Committee at Porsche AG decided to also increase the torque specification for all future series production vehicles with center locking wheel and hub assemblies. The new bolts without the torque inscription, and the new tightening torque specification were introduced into production on September 16, 2010.

December 2010 - March 2011

No further reports on incidents from race tracks and no reports of broken center locking wheel and hub assemblies from the field.

March 2011 - April 2011

With the start of the new racing season, customers required information on why there are different torque requirements for the center locking wheel and hub assembly for racing conditions (600 Nm per the above) and for public road use (500 Nm per the inscription on the center wheel bolt). Consideration by the Product Safety Committee at Porsche AG that the subject differences can only be addressed through a recall, even though there were no reported field cases during public road use.

June 9, 2011

PART 573 Defect and Noncompliance Report (Update)

Date of determination: April 29, 2011

7. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.

Not applicable.

V. Identify the Remedy

8. Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.

The affected vehicles will be recalled to the workshop and the central bolts will be replaced and fitted in accordance with the new greasing specification. A new owner's manual supplement will also be added to the vehicles documentation portfolio. In addition, any mating components will be inspected and replaced as necessary.

Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

The originally installed bolts bear an inscription of the previously required tightening torque specification. The replacement bolts no longer bear this inscription.

Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

The new bolts (without the imprinting) were introduced into production on September 16, 2010. This is also the date of how the recall population was determined. The production solution (new bolts and the fitting in accordance with the new greasing specification) is identical to the recall remedy in the field.

June 9, 2011 Page 7 of 8

PART 573 Defect and Noncompliance Report (Update)

VI. Identify the Recall Schedule

Furnish a schedule or agenda (with specific dates) for notification to dealers and purchasers.

To be determined.

VII. Furnish Recall Communications

9. Furnish a final copy of all notices, bulletins, and other communications that relate directly to the defect or noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications (including both original and follow-up) concerning this recall from the time your company determines the defect or noncompliance condition on, not just the initial notification.

Attached is a draft of the draft copy of the Technical Information Bulletin. Also attached is a Part Information Bulletin requesting the affected parts be returned to PCNA from dealer inventory.

June 9, 2011