



TECHNICAL SERVICE BULLETIN

THE NEW AMERICAN MOTORCYCLE™

Date: 06/13/2011

Victory Motorcycle

Bulletin Number: V-11-01
V-11-01A
Model Years: 2011

Safety Bulletin Safety Recall Service Bulletin Service Alert Fax Production Update Kit

Distribution: Owner / Principal Service Manager Sales Manager Parts Manager Technicians

This Service Bulletin is located at www.polarisdealers.com

-Confidential and Proprietary-



SUBJECT: 2011 Cross Country Handlebar Riser Assembly Inspection / Replacement

PURPOSE:

Victory has determined that some Model Year 2011 Victory Cross Country handlebar riser / clamp assemblies may be defective. The defective handlebar riser / clamp assemblies do not provide sufficient clamping force and may allow the handlebars to rotate in the riser assembly, increasing the risk of an operator losing control which could result in a vehicle crash.

AFFECTED MODELS:

| Model(s) Affected | Model Numbers | Vehicle Identification Number Range |
|----------------------------|--|---|
| 2011 Victory Cross Country | V11DB36EA; V11DB36EB; V11DB36ER; V11DB36NA; V11DB36NAA; V11DB36NAC; V11DB36NB; V11DB36NBA; V11DB36NBC V11DB36NR; V11DB36NRA; V11DB36NRC V11DC36EN; V11DC36NN; V11DC36NNA V11DC36NNC; V11EB36EA; V11EB36EC; V11EB36EY | Vehicles built between 01/01/11 – 04/09/11 Reference 'Unit Inquiry' on the dealer website to lookup affected VIN's. |

WHAT YOUR DEALERSHIP SHOULD DO:

1. Perform the INSPECTION PROCEDURE outlined in this bulletin to determine if handlebar riser / clamp assemblies are defective.
2. If the vehicle passes inspection, file a warranty claim for bulletin V-11-01 immediately following completion.
3. **If the INSPECTION PROCEDURE reveals defective handlebar riser / clamp assemblies dealers should;**
 - Replace handlebar riser / clamp assemblies following the REPLACEMENT PROCEDURE outlined in this bulletin.
 - File a warranty claim for bulletin V-11-01A immediately after completion of this bulletin.
4. Dealer must submit an ASK Polaris case via **Warranty Claim & Warranty Parts Return Question** and provide the following information;
 - Warranty Claim Number for bulletin V-11-01A.
 - The words "V-11-01A Repair Order" must be written in the **Question** field.
 - A copy of your Dealership's Customer Repair Order must be attached to the ASK Polaris case.

NOTE: Polaris will be working with an outside company, Centro Inspection Agency, to assist with vehicle field inspection audits when necessary.

CUSTOMER NOTIFICATION:

A customer notification letter will be sent to all registered owners of motorcycles affected by this bulletin. An example of the U.S. letter is shown on page 8. In addition to the notification letter sent by Victory Motorcycles, dealers are required to notify owners of motorcycles sold by their dealership, and to make arrangements to perform this bulletin repair immediately.

INSPECTION PROCEDURE:

Tools Required for Inspection:



- (QTY.2) Soft tie straps with a minimum 50 lbs. load rating (commercially available).
- (QTY.2) Spring-scale with a 50 lbs. weight rating (commercially available).

1. Support motorcycle securely in an upright position with the front wheel clamped in a wheel vise.
2. Using a grease pen, mark the handlebar at the parting line between the riser and riser clamp (see Figure 1). The mark will be used to determine if any handlebar rotation has occurred following the inspection.
3. Securely attach tie straps around center of left and right handgrips (see Figure 2).
4. Attach the spring scales to the tie straps (see Figure 2).

5. With one person on each side of the motorcycle, slowly apply an upward (vertical lifting) force until each scale individually reads 50 lbs. (Force totaling 100 lbs. on the handlebar assembly).


THE HANDLEBAR ASSEMBLY SHOULD NOT ROTATE WITHIN THE RISERS. IF ANY MOVEMENT IS DETECTED THE RISER / CLAMP ASSEMBLIES MUST BE REPLACED (PROCEED TO REPLACEMENT PROCEDURE).

6. If no rotation is detected, the replacement procedure is not necessary. File a warranty claim for V-11-01 (Inspection).




REPLACEMENT PROCEDURE:


1. Remove head light bezel (see Figure 1).




2. Remove screws (4) securing head light assembly to front fairing (see Figure 2), disconnect electrical connectors and remove head light.




3. Using body tool (PV-49955), remove left and right speaker grills from front fairing as shown (see Figure 3).



4. Remove screws (8) securing outer fairing shell to fairing subassembly (see Figure 4). Disconnect turn signal connectors and remove outer fairing shell.




5. Remove bolts (4) securing fairing subassembly to chassis (see Figure 5).



6. Lift subassembly and tilt forward to gain access to handlebar risers and clamp bolts (see Figure 6).

CAUTION: Wires may become stretched, kinked or broken if extreme care is not taken while maneuvering subassembly.



7. Place a protective cover over the fuel tank. While supporting the handlebar assembly, remove the handlebar clamp bolts (see Figure 7).

IMPORTANT: If the handlebar assembly is not properly supported, the handlebar may drop down onto the fuel tank when the clamp bolts are loosened. If the fuel tank is not sufficiently protected, damage may occur.

8. Lift the handlebar assembly out of risers and move forward until clear of risers (see Figure 8).

9. Loosen set screws securing riser bolts and remove bolts (1 each) securing handlebar risers to upper triple clamp (see Figure 8).

10. Remove risers.

11. Loosely install new handlebar risers. Place the handlebar assembly into risers to maintain riser alignment. Torque riser bolts to **40 ft-lbs. (54 Nm)**.

12. Tighten set screw (see Figure 8) until it stops against riser bolt then tighten an additional **90° (1/4 turn)**.

13. Loosely install new riser clamps and clamp bolts, so the handlebar can rotate freely in risers.

14. Align the index mark on the handlebar with the parting in the riser clamp (see Figure 9). Starting with the front bolts, torque riser clamp bolts to **22 ft-lbs. (30 Nm)**.

15. Reinstall fairing subassembly bolts (see Figure 5). Torque bolts to **19 ft-lbs. (26 Nm)**.

16. Lift outer fairing shell into position and reconnect turn signals (see Figure 4). Torque screws to **36 in-lbs. (4 Nm)**.

17. Reinstall speaker grills, head light assembly and head light bezel.

18. Verify the following:

- Handlebars turn freely from left to right.
- Turn signals operate properly.
- High-beam and Low-beam head lights operate correctly.
- Side mirrors are adjusted correctly.

19. File a warranty claim for V-11-01A and submit an ASK Polaris case via **Warranty Claim & Warranty Parts Return Question** and provide the following information:

- Warranty Claim Number for bulletin V-11-01A.
- The words "V-11-01A Repair Order" must be written in the **Question** field.
- A copy of your Dealership's Customer Repair Order must be attached to the ASK Polaris case.



Figure 7




Figure 8




Figure 9

PARTS INFORMATION:

V-11-01 (INSPECTION)

| | |
|----------------------------------|--|
| PART NUMBER / DESRIPTION | 7170107 (QTY. 1) – Service Bulletin Completion Decal |
| PARTS AVAILABILITY | Available to Order |
| DIRECT-SHIP FROM POLARIS? | No |
| TO BE ORDERED BY DEALER? | Yes |

V-11-01A (INSPECTION AND REPLACEMENT)

| | |
|----------------------------------|---|
| PART NUMBER / DESRIPTION | 5136703-468 (QTY. 2) - Handlebar Riser (Black) 5136704-468 (QTY. 2) - Handlebar Clamp (Black) 7519100 (QTY. 2) – Set Screw 7519044 (QTY. 2) – Riser Bolt 7517569 (QTY. 4) – Clamp Screw 7170107 (QTY. 1) – Service Bulletin Completion Decal |
| PARTS AVAILABILITY | Parts available to order on the week of 6/13/2011. |
| DIRECT-SHIP FROM POLARIS? | No |
| TO BE ORDERED BY DEALER? | Yes |

WARRANTY CLAIM INFORMATION:

A single group claim may be submitted listing the complete (17 digit) Vehicle Identification Number for machines with the same model number. File claim type **SB (Service Bulletin)**. DO NOT PUT MORE THAN ONE MODEL NUMBER ON A CLAIM.

| | |
|---------------------------|-----------------------------|
| SERVICE BULLETIN # | V-11-01 (Inspection) |
| CLAIM TYPE | SB (Service Bulletin) |
| LABOR ALLOWANCE | .2 Hrs. (12 minutes) |
| CLAIM PART NUMBERS | N/A - Auto Process Bulletin |

| | |
|---------------------------|---|
| SERVICE BULLETIN # | V-11-01A (Inspection and Replacement) |
| CLAIM TYPE | SB (Service Bulletin) |
| LABOR ALLOWANCE | 1.4 Hrs. (1 hour :24 minutes) *Time includes inspection* |
| CLAIM PART NUMBERS | 5136703-468 (QTY. 2) - Handlebar Riser (Black) 5136704-468 (QTY. 2) - Handlebar Clamp (Black) 7519100 (QTY. 2) – Set Screw 7519044 (QTY. 2) – Riser Bolt 7517569 (QTY. 4) – Clamp Screw 7170107 (QTY. 1) – Service Bulletin Completion Decal |

SERVICE BULLETIN COMPLETION DECAL:

A Service Bulletin Completion Decal must be completed for this bulletin repair. Place the decal on the unit as shown (inside LH side cover). If you require more decals, order them through normal Polaris parts ordering channels.

Sincerely,



Bridget McLennan,
Warranty and Service Publications Manager

