

On-scene Investigation / Vehicle to Vehicle
Dynamic Science, Inc. / Case Number: DS00-002
2000 Ford Taurus
California
February, 2000

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

Technical Report Documentation Page

1. Report No. DS00-002		2. Government Accession No.		3. Recipient Catalog No.	
4. Title and Subtitle In-Depth Accident Investigation				5. Report Date November 15, 2000	
				6. Performing Organization Report No.	
7. Author(s) Dynamic Science, Inc.				8. Performing Organization Report No.	
9. Performing Organization name and Address Dynamic Science, Inc. 530 College Parkway, Ste. K Annapolis, MD 21401				10. Work Unit No. (TRAIS)	
				11. Contract or Grant no. DTNH22-94-D-27058	
12. Sponsoring Agency Name and Address U.S. Dept. of Transportation (NRD-32) National Highway Traffic Safety Administration 400 7th Street, SW Washington, DC 20590				13. Type of report and period Covered [Report Month, Year]	
				14. Sponsoring Agency Code	
15. Supplemental Notes					
16. Abstract This three vehicle crash occurred in California in February, 2000 at 1340 hours. The crash took place on the four northbound travel lanes of an interstate highway. The posted speed limit is 89 km/h (55 mph). There was heavy traffic on this roadway. The case vehicle, a 2000 Ford Taurus 4-door driven by an unrestrained 70-year-old female, was traveling northbound in the second lane from the right. The front right seat was occupied by an unrestrained 69-year-old male. The second vehicle in the crash, a 1993 Nissan Sentra driven by a 26-year-old female, was traveling northbound in the fourth lane from the right. The third vehicle in this crash, a 1997 Cadillac DeVille driven by a 70-year-old female, was traveling northbound in the first lane from the right. The front right seat was occupied by a 78-year-old male. The right rear seat was occupied by an 80-year-old female. As the driver of the Nissan Sentra approached slowing traffic in front of her, the traffic apparently abruptly stopped. The driver of the Sentra braked and swerved to the right. She crossed the adjacent travel lane and then entered the lane being used by the case vehicle. The Nissan Sentra struck the left front of the case vehicle. The case vehicle went out of control to the right. The vehicle entered the next lane to the right and was struck by the Cadillac DeVille in the right side. The Cadillac veered to the right and struck a sound wall. The case vehicle also continued to the right and struck the sound wall. The case vehicle then rolled backwards across the travel lanes and struck the center median barrier with its rear end. The driver of the case vehicle sustained facial fractures, dislocated teeth, soft tissue injuries, a neck strain, a 4 in. laceration to the forehead above the left eye, a broken nose, an unknown type injury to her right heel, and a contusion to the left knee. The front right occupant of the case vehicle sustained contusions to both knees. The driver and front right occupant of the case vehicle were transported to a local hospital. The driver was hospitalized. The front right occupant was treated and released after 9 hours. The driver of the Sentra complained of pain to her neck, back, and legs. She indicated that she would seek her own aid. The driver and front right occupant of the Cadillac were not injured. The rear right occupant complained of pain to both legs, but indicated that she would seek her own aid.					
17. Key Words Air bag, deployment, AOPS, injury, side air bag, passenger			18. Distribution Statement		
19. Security Classif. (of this report)		20. Security Classif. (of this page)		21. No of pages	22. Price

Dynamic Science, Inc.
Accident Investigation
Case Number: DS00-002

TABLE OF CONTENTS

Background 1
 Description 1
 Investigation Type 1
 Crash Location 1
 Crash Date 1
 Notification Date 1
 Field Work Completed 1

Summary 1

Scene Diagram 6

Detailed Information 8
 Vehicles 8
 Occupants 11
 Injuries and Injury Mechanisms 14
 Occupant Kinematics 16

BACKGROUND:

Description: This Advanced Occupant Protection Systems (AOPS) case was generated by DSI through existing insurance contacts. NHTSA was notified of the case on June 21, 2000. DSI was assigned the case on June 22, 2000. Field work was completed on June 24, 2000.

Investigation Type: On scene

Crash Location: California
 Crash Date: February, 2000
 Notification Date: June 21, 2000
 Field Work Completed: June 24, 2000

SUMMARY:

This three vehicle crash occurred in California in February, 2000 at 1340 hours. The crash took place on the four northbound travel lanes of an interstate highway. There is an uphill grade and a slight left hand curve at the crash location. The weather was relatively clear and there were no roadway defects indicated. The posted speed limit is 89 km/h (55 mph). There was heavy traffic on this roadway.

The case vehicle, a 2000 Ford Taurus 4-door driven by an unrestrained 70-year-old female (163 cm/64 in., 59 kg/130 lbs) , was traveling northbound in the second lane from the right. The front right seat was occupied by an unrestrained 69-year-old male (188 cm/74 in., 125 kg/275 lbs). The Ford Taurus was equipped with front left and front right frontal air bags, front left and front right side air bags, seat belt pretensioners at the front left and front right seating positions, and adjustable foot controls. While this vehicle had been driven 13,101 km (8,141 miles), the dealer sticker was still in the left rear window and the plastic protective covers on the floorboard had not been removed.



Figure 1. Overview of vehicle paths. Crash occurred 640 m (2100 ft) north. Arrow shows approximate area of impact.



Figure 2. Front view of case vehicle (2000 Ford Taurus)

The second vehicle in the crash, a 1993 Nissan Sentra driven by a 26-year-old female, was traveling northbound in the fourth lane from the right.

The third vehicle in this crash, a 1997 Cadillac DeVille driven by a 70-year-old female, was traveling northbound in the first lane from the right. The front right seat was occupied by a 78-year-old male. The right rear seat was occupied by an 80-year-old female.

As the driver of the Nissan Sentra approached slowing traffic in front of her, the traffic apparently abruptly stopped. The driver of the Sentra braked and swerved to the right. She crossed the adjacent travel lane and then entered the lane being used by the case vehicle. The Nissan Sentra struck the left front of the case vehicle (12LYES1). The case vehicle went out of control to the right. The vehicle entered the next lane to the right and was struck by the Cadillac DeVille in the right side (04RPEW3). The case vehicle sustained a longitudinal delta v of 6.2 km/h (3.9 mph) and a latitudinal delta v of (-10.8 km/h (-6.7 mph))¹. The passenger side air bag deployed at this point. The Cadillac veered to the right and struck a sound wall. The case vehicle also continued to the right and struck the sound wall (12FDEW1). The case vehicle sustained a longitudinal delta v of -18.7 km/h (-11.6 mph) and a latitudinal delta v of 1.6 km/h (1.0 mph)². Both front air bags deployed at this point. An Electronic Data Recorder report was generated for this vehicle. The results indicate that the vehicle had a longitudinal cumulative delta v of -14.0 mph at the 78 millisecond mark. The case vehicle then rolled backwards across the travel lanes and struck the center median barrier with its rear end.

The driver of the case vehicle sustained facial fractures, dislocated teeth, soft tissue injuries, a neck strain, a 4 in. laceration to the forehead above the left eye, a broken nose, an unknown type injury to her right heel, and a contusion to the left knee.



Figure 3. Exterior, case vehicle. Shows impact #1.



Figure 4. Exterior, case vehicle. Shows impact #2.

¹Calculated using WinSmash missing vehicle program

²Calculated using barrier option and using stiffness values from NCAP test

The front right occupant of the case vehicle sustained contusions to both knees. He also complained of pain to his chest, rib cage, neck, and shoulders.

The driver and front right occupant of the case vehicle were transported to a local hospital. The driver was hospitalized. The front right occupant was treated and released after 9 hours.

The driver of the Sentra complained of pain to her neck, back, and legs (muscle spasms). She indicated that she would seek her own aid.

The driver and front right occupant of the Cadillac were not injured. The rear right occupant complained of pain to both legs, but indicated that she would seek her own aid.

The Ford Taurus and the Cadillac DeVille were towed from the scene. The Nissan Sentra was driven from the scene.



Figure 5. Driver's frontal air bag

The case vehicle was equipped with front left and front right frontal air bags, front left and front right side air bags, seat belt pretensioners at the front left and front right seating positions, and adjustable foot controls.

The driver's air bag was circular and measured 54 cm (21.2 in.) in diameter. It was equipped with two tethers and two vent holes. There appeared to be eight horizontal folds. Blood was found on the top right quadrant. On the bottom of the rear portion of the air bag there was lipstick and makeup transfers that measured 15 cm (5.9 in.) wide by 11 cm (4.3 in.) high. The module cover opened in an "H" configuration. There were no indications of any damage to the cover.

The front right occupant's frontal air bag was rectangular and measured 60 cm (23.6) laterally. It was equipped with two vent ports and did not have any tethers. On the face of the air bag there was a diagonal plastic transfer that began at the bottom of the air bag, extended for 26 cm (10.2) up and to the right and ended up being 11 cm (4.3) across. The right hand longitudinal seam was measured at 13 cm (5.1 in), while the left hand side measured 9 cm (3.5 in.). The module itself was displaced vertically on the left side.




Figure 6. Front passenger air bag module cover



Figure 7. Passenger module cover displacement

The front right seat position was equipped with a seat-mounted side air bag. The air bag was equipped with a single tether and no vent ports. The bag is vaguely rectangular and measures 64 cm (25 in.) high by 29 cm (11.4 in.) wide at its base. There was no indication of a contact to the air bag nor any damage.

Both front seat positions were equipped with seat belt pretensioners. The pretensioner barrels were checked and measured 11 cm (4.3 in.), indicating that they had not deployed.

The data from the RCM module was downloaded. It indicated that neither front seat buckles were engaged and that a first stage deployment had occurred.



Figure 8. Right front side air bag

Scene Diagram




Figure 9. Scene diagram (1 of 2)




Figure 10. Scene diagram (2 of 2)

DETAILED INFORMATION**Vehicles**2000 Ford Taurus

Description:	2000 Ford Taurus four-door	
VIN:	1FAFP56S0YGxxxxxx	
Odometer:	13,101 km (8,141 miles)	
Engine:	6 cyl / 182 CID	
Reported Defects:	None	
Cargo:	None	
Damage Description:	Moderate rearward crush to front bumper. Rubber transfer to left front quarter panel. Lateral crush to right rear door; side glass broken out.	
CDC:	Impact #1: 12LYES01 Impact #2: 04RPEW03 Impact #3: 12FDEW01 Impact #4: 06BRLN01	
Delta V (Impact #3):	Total	18.7 km/h (11.6 mph)
	Longitudinal	-18.7 km/h (-11.6 mph)
	Latitudinal	1.6 km/h (1.0 mph)
	Energy	23,170 joules (17,088 ft-lbs)
Delta V (Impact #2)	Total	12.4 km/h (7.7 mph)
	Longitudinal	6.2 km/h (3.3 mph)
	Latitudinal	-10.8 km/h (-6.7 mph)
	Energy	11,840 joules (8,732 ft-lbs)

1993 Nissan Sentra

Description:	1993 Nissan Sentra	
VIN:	Unknown	
Odometer:	Unknown	
Engine:	Unknown	
Reported Defects:	None noted	
Cargo:	Unknown	
Damage Description:	Unknown	
CDC:	Unknown	
Delta V:	Total	Unknown
	Longitudinal	Unknown
	Latitudinal	Unknown
	Energy	Unknown

1997 Cadillac DeVille

Description:	1997 Cadillac DeVille	
VIN:	Unknown	
Odometer:	Unknown	
Engine:	Unknown	
Reported Defects:	None	
Cargo:	Unknown	
Damage Description:	Unknown	
CDC:	Unknown	
Delta V (Impact #2 - case vehicle):	Total	12.0 km/h (7.5 mph)
	Longitudinal	-12.0 km/h (-7.5 mph)
	Latitudinal	0 km/h (0 mph)
	Energy	7,582 joules (5,592 ft-lbs)

Occupants

<u>Ford Taurus</u>	Occupant 1	Occupant 2
Age/Sex:	70/Female	69/Male
Seated Position:	Front left	Front right
Seat Type:	Cloth-covered bucket seat	Cloth-covered bucket seat
Height:	163 cm (64 in)	188 cm (74 in.)
Weight:	59 kg (130 lbs)	125 kg (275 lbs)
Occupation:	Presumed to be retired	Presumed to be retired
Pre-existing Medical Condition:	None noted	None noted
Alcohol/Drug Involvement:	None	NA
Driving Experience:	> 30 years	NA
Body Posture:	Normal, upright	Possibly out of position. Prior to impact was trying to reach something in rear seat.
Hand Position:	Both hands on wheel, unknown position	NA
Foot Position:	Right foot on brake, left on floor	Unknown—presumed to be on floor
Restraint Usage:	Lap and shoulder belts available—not used	Lap and shoulder belts available—not used
Air bag:	Left steering wheel mounted front air bag deployed.	Right mid instrument panel mounted air bag deployed. Right seat mounted side air bag deployed.

Nissan Sentra

Age/Sex:	26/Female
Seated Position:	Front left
Seat Type:	Unknown
Height:	165 cm (65 in)
Weight:	91 (200 lbs)
Occupation:	Unknown
Pre-existing Medical Condition:	Unknown
Alcohol/Drug Involvement:	None
Driving Experience:	Unknown, presumed to be around 10 years
Body Posture:	Unknown
Hand Position:	Unknown
Foot Position:	Unknown
Restraint Usage:	Lap and shoulder belt used

Cadillac DeVille

Age/Sex:	70/Female	79/male	80/Female
Seated Position:	Front left	Front right	Rear right
Seat Type:	Unknown	Unknown	Unknown
Height:	165 cm (65 in)	Unknown	Unknown
Weight:	82 kg (180 lbs)	Unknown	Unknown
Occupation:	Presumed to be retired	Presumed to be retired	Presumed to be retired
Pre-existing Medical Condition:	Unknown	Unknown	Unknown
Alcohol/Drug Involvement:	None	NA	NA
Driving Experience:	Unknown	NA	NA
Body Posture:	Unknown	Unknown	Unknown
Hand Position:	Unknown	Unknown	Unknown
Foot Position:	Unknown	Unknown	Unknown
Restraint Usage:	Lap and shoulder belt used	Lap and shoulder belt used	Lap and shoulder belt used

Injuries and Injury Mechanisms

Ford Taurus

	<u>INJURY</u>	<u>OIC CODE</u>	<u>ICD-9</u>	<u>SOURCE</u>
Driver:	Blowout fracture, left orbit	251204.3,2	802.8	Air bag
	Dislocated teeth	251402.1,8	873.69	Air bag
	Forehead laceration, left side, 4 inches	290804.2,7	873.42	Air bag
	Nose fracture	251000.1,4	959.0	Air bag
	Contusion, left knee	890402.1,2	924.11	Lower instrument panel
	Heel injury, right foot	815099.7,1	917.8	Floor board
FR Occupant:	Bilateral knee contusions	890402.1,1 890402.1,2	924.11 924.11	Lower instrument panel
	Complaint of pain to chest, rib cage, neck, and shoulders.	Not codeable		

1993 Nissan Sentra

	<u>INJURY</u>	<u>OIC CODE</u>	<u>ICD-9</u>	<u>SOURCE</u>
Driver:	Complaint of pain to neck, back, and legs.			

1997 Cadillac DeVille

	<u>INJURY</u>	<u>OIC CODE</u>	<u>ICD-9</u>	<u>SOURCE</u>
Driver:	Not injured			
Front right occupant:	Not injured			
Rear right occupant	Not injured			

Occupant Kinematics

The driver of the case vehicle was seated in a normal, upright position. She does not appear to have been wearing the available lap and shoulder belt. There were indications of usage, but nothing related to this crash. The pretensioner barrels were checked and measured 11 cm (4.3 in.), indicating that they had not deployed. The data from the RCM module was downloaded and it indicated that neither front seat buckle was engaged. There was negligible driver movement during the initial sideswiping type impact on the left side of the vehicle. The driver steered to the right in response to the impact. The rear right side of the vehicle was struck by the Cadillac and the driver would have moved slightly to the right side. As the case vehicle struck the concrete wall, the driver responded to the 355 degree principal direction of force by moving essentially straight forward.

Both of the driver's knees struck the lower instrument panel—causing the contusion to the left knee. The driver's face was close to the steering wheel and as the air bag deployed she engaged the back side of the air bag. This contact likely caused the facial injuries, including the blow-out fracture, the broken nose, and the forehead laceration.

The front right occupant was originally seated in a normal, upright position. According to the interviewee, prior to the impact he had removed his seat belt and was reaching for something in the rear seat. He was not using the available lap and shoulder belt. His movement during the first minor impact would have been similar to that of the driver's. During the second impact, the side air bag deployed and this occupant likely contacted it to some degree, though there was no evidence of any specific contact. As the case vehicle continued on and struck the concrete wall, this occupant responded to the 355 degree principal direction of force by moving essentially straight forward. Both of this occupant's knees struck the glove compartment. This occupant sustained contusions to both knees. He also complained of pain to his chest, rib cage, neck, and shoulders.



Figure 11. Left knee contact to lower instrument panel.



Figure 12. Driver's air bag. Contact points to back side of air bag.

EDR Report

2000 Taurus/Sable EDR Report - Summary Page

Investigation Data

File Name:	ds00-002.hex	File Save Date:	29-Jun-2000
File Read-out Date:	N/A	Report Date:	20-Oct-2000
Report Version:	1.4		

EDR Control Module Data

Data Validity Check:	Valid	EDR Model Version:	141
Time From Side Safing Decision to Left (Driver) Side Bag Deployment:			Not Deployed
Time From Side Safing Decision to Right (Passenger) Side Bag Deployment:			96
Passenger Airbag Switch Position During Event:			N/A
Diagnostic Codes Active When Event Occurred:			0

Algorithm Times

Actual initiation depends on restraint system status (below).

	ms
Time From Algorithm Wakeup to Pretensioner:	26
Time From Algorithm Wakeup to First Stage - Unbelted:	26
Time From Algorithm Wakeup to First Stage - Belted:	26
Time From Algorithm Wakeup to Second Stage:	0

Restraint System Status

Driver Seat Belt Buckle:	Not Engaged
Passenger Seat Belt Buckle:	Not Engaged
Driver Seat Track In Forward Position:	No
Passenger Seat Weight Switch Position:	N/A

Deployment Initiation Attempt Times

	Driver	Passenger
Time From Algorithm Wakeup to Pretensioner Deployment Attempt:	Unbelted	Unbelted
Time From Algorithm Wakeup to First Stage Deployment Attempt:	26	26
Time From Algorithm Wakeup to Second Stage Deployment Attempt:	Disposal	Disposal


Notes

1. Read-out date is set by the PC interface tool.
2. Features and data parameters which are not available on the module are marked "N/A".
3. CFC 60 is a Butterworth 4-pole phaseless digital filter. (See SAE J211 Part 1 Appendix C dated March 1995.)
4. Total and maximum Delta-V results are not available from truncated/incomplete crash pulses.
5. Algorithm wakeup (0 ms) is not the first moment of vehicle contact or impact.
6. The Excel "Analysis ToolPak" Add-in must be enabled for this spreadsheet to operate properly.

2000 Taurus/Sable EDR Report - Charts


Longitudinal Cumulative Delta-V

Time (ms)	0	10	20	30	40	50	60	70	78
Delta-V (MPH)	-0.4	-2.3	-4.2	-5.6	-7.4	-8.3	-10.2	-12.0	-14.0



Lateral Cumulative Delta-V

Time (ms)	0	10	20	30	40	50	60	70	78
Delta-V (MPH)	0.3	0.6	0.7	0.5	0.2	-0.4	-0.2	0.0	0.0



File Name: ds00-002.hex