On-scene Investigation / Vehicle to Vehicle
Dynamic Science, Inc. / Case Number: DS00005
2000 Mercury Sable LS
Texas
March, 2000

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the precrash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

			Technical Report Documentation Page	
1. Report No.	2. Government Accession No.		3. Recipient Catalog No.	
DS00005				
4. Title and Subtitle In-Depth Accident Investigation			5. Report Date	
			January 17, 2001	
			6. Performing Organization Report No.	
7. Author(s) Dynamic Science, Inc.			8. Performing Organization Report No.	
9. Performing Organization name and Address			10. Work Unit No. (TRAIS)	
Dynamic Science, Inc.				
530 College Parkway, Ste. K			11. Contract or Grant no.	
Annapolis, MD 21401			DTNH22-94-D-27058	
12. Sponsoring Agency Name and Address			13. Type of report and period Covered	
U.S. Dept. of Transportation (NRD-32)			[Report Month, Year]	
National Highway Traffic	c Safety Administration		14 Secreting Agency Code	
400 7th Street, SW			14. Sponsoring Agency Code	
Washington, DC 20590				
15. Supplemental Notes				
16. Abstract				
The crash occurred in Texas in March, 2000 at 1720 hours. The crash took place at a four-leg intersection. The southbound leg of the intersection is comprised of two, unmarked one-way travel lanes. There is a 2% positive grade at this location. Traffic is controlled by a stop sign. The speed limit is 48 km/h (30 mph). The westbound leg of the intersection is comprised of three one way travel lanes. The roadway is level at this location. The northernmost two lanes continue through the intersection and continue as an access to a freeway. The southern lane is for left turning traffic only and is separated from the other lanes by a raised grass-covered median. The speed limit is 56 km/h (35 mph).				
The case vehicle, a 2000 Mercury Sable LS 4-door sedan driven by a restrained 40-year-old male, was traveling southbound. The front right seat was occupied by a 20-year-old female. The other vehicle, a 1986 Honda Accord driven by an 18-year-old male, was traveling westbound.				
The driver of the case vehicle stopped at the intersection and did not yield the right of way to the other vehicle. As the case vehicle entered the intersection at a speed estimated to be 16 km/h (10 mph), the front of the case vehicle (10FYEW1) struck the right side of the other vehicle.				
The impact was of insufficient magnitude to deploy the driver's air bag and the front right passenger's air bag. The driver's side seat belt pretensioners also did not fire at this time. The pretensioner tube measurement for the driver was 11 cm; for the passenger the measurement was 11.2 cm. There was no movement of the steering column shear capsules.				
The case vehicle sustained a longitudinal delta v of -3.1 km/h (-1.9 mph) and a lateral delta v of 8.5 km/h (5.3 mph).				
The center console of the case vehicle was displaced somewhat–possibly by the left leg of the front right seat occupant. There were, however, no injuries reported by any of the parties involved. Both vehicles were towed from the scene due to the damage.				
17. Key Words		18. Distribution Statement		
Air bag, non deployment,	advanced, no injury			
19. Security Classif. (of this report)	20. Security Classif. (of this page)	21. No of pages	22. Price	

Form DOT F 1700.7 (8_72) Reproduction of this form and completed page is authorized

Dynamic Science, Inc. Accident Investigation Case Number: DS00005

TABLE OF CONTENTS

Background	1		
Description	1		
Investigation Type	1		
Crash Location			
Crash Date	1		
Notification Date	1		
Field Work Completed	1		
Summary	1		
Scene Diagram	4		
Detailed Information	5		
Vehicles	5		
Occupants	7		
Injuries and Injury Mechanisms			
Occupant Kinematics			

Attachment 1. Speed calculations

BACKGROUND:

Description: This Advanced Occupant Protection Systems case was generated by

DSI through existing insurance contacts. NHTSA was notified of the case on July 06, 2000. DSI was assigned the case on July 06, 2000

and an on-site investigation was conducted.

Investigation Type: On-scene

Crash Location: Texas

Crash Date: March, 2000 Notification Date: July 6, 2000 Field Work Completed: July 7, 2000

SUMMARY:

The crash occurred in Texas in March, 2000 at 1720 hours. The crash took place at a four-leg intersection.

The southbound leg of the intersection is comprised of two, unmarked one-way travel lanes. There is a 2% positive grade at this location. Traffic is controlled by a stop sign. The speed limit is 48 km/h (30 mph).

The westbound leg of the intersection is comprised of three one way travel lanes. The roadway is level at this location. The northernmost two lanes continue through the intersection and continue as an access to a freeway. The southern lane is for left turning traffic only and is separated from the other lanes by a raised grass-covered median. The speed limit is 56 km/h (35 mph).

The weather was clear and the asphalt roadways were dry and free of defects.



Figure 1. Path of case vehicle (Mercury Sable) to area of impact



Figure 2. Path of other vehicle (Honda Accord) to area of impact

The case vehicle, a 2000 Mercury Sable LS 4-door sedan driven by a restrained 40-year-old male, was traveling southbound. The front right seat was occupied by a restrained 20-year-old female.

The other vehicle, a 1986 Honda Accord driven by an 18-year-old male, was traveling westbound.

The driver of the case vehicle stopped at the intersection and did not yield the right of way to the other vehicle. As the case vehicle entered the intersection at a speed estimated to be 16 km/h (10 mph)¹, the front of the case vehicle (10FYEW1) struck the right side of the other vehicle.

The impact was of insufficient magnitude to deploy the driver's air bag and the front right passenger's air bag. The driver's side seat belt pretensioners also did not fire at this time. The pretensioner tube measurement for the driver was 11 cm; for the passenger the measurement was 11.2 cm. There was no movement of the steering column shear capsules.

The case vehicle sustained a longitudinal delta v of - 3.1 km/h (-1.9 mph)² and a lateral delta v of 8.5 km/h (5.3 mph) as computed by WinSmash. The RCM



Figure 3. Case vehicle, front view



Figure 4. Vehicle 1, front right view

data was downloaded and forwarded to Ford. On August 29, 2000, Ford indicated that: "The crash events for the SCI investigation of case DS00-005 were not recorded by the Restraints Control Module. Therefore, no information about the crash pulse, or other conditions is available."

The center console of the case vehicle was displaced somewhat–possibly by the left leg of the front right seat occupant. There were, however, no injuries reported by any of the parties involved.

¹Calculated using a travel distance of 27 ft and an acceleration rate of 4 ft/sec/sec

²Calculated using stiffness values from NCAP tests

Both vehicles were towed from the scene due to the damage.




Figure 5. Driver's seated area



Figure 6. Front right occupant seated area

Scene Diagram



DETAILED INFORMATION

Vehicles

Case vehicle

Description: 2000 Mercury Sable LS four-door

VIN: 1MEFM55S1YGxxxxxx

Odometer: 11,329 km (7,040 miles)

Engine: V6/3.0 L

Reported Defects: None

Cargo: None

Damage Description: Minor bumper contact, minor contact damage to

left fender. Towed from the scene.

CDC: 10FYEW1

Delta V: Total 9.0 km/h (5.6 mph)

Longitudinal -3.1 km/h (-1.9 mph)

Latitudinal 8.5 km/h (5.3 mph)

Energy 4,668 joules

(3,444 ft-lbs)



Figure 8. Exterior, case vehicle



Figure 9. Exterior, left side, case vehicle

Other vehicle

Description: 1986 Honda Accord four door

VIN: JHMBA7435GCxxxxxx

Odometer: Unknown

Engine: Unknown

Reported Defects: None noted

Cargo: Unknown

Damage Description: Moderate damage to front right fender. Towed

from the scene.

CDC: Unknown

Delta V: Total 12.4 km/h (7.7 mph)

Longitudinal -11.2 km/h (-7.0 mph)

Latitudinal -5.2 km/h (-3.2 mph)

Energy 19,519 joules

(14,397 ft-lbs)

Occupants

<u>Vehicle 1</u> Occupant 1 Occupant 2

Age/Sex: 40/Male 20/Female

Seated Position: Front left Front right

Seat Type: Bucket Bucket

Height: Unknown Unknown

Weight: Unknown Unknown

Occupation: Business owner Unknown

Pre-existing Medical Condition: None noted None noted

Alcohol/Drug Involvement: None NA

Driving Experience: Unknown NA

Body Posture: Presumed to be normal, Presumed to be normal, upright

upright

Hand Position: Unknown Unknown

Foot Position: Left on floorboard, right on Unknown

accelerator

Restraint Usage: Lap and shoulder belt used Lap and shoulder belt used

Air bag: Available, not deployed Available, not deployed

Occupants

Vehicle 2

Age/Sex: 18/Male

Seated Position: Front left

Seat Type: Bucket

Height: Unknown

Weight: Unknown

Occupation: Unknown

Pre-existing Medical Condition: None noted

Alcohol/Drug Involvement: None

Driving Experience: Unknown

Body Posture: Unknown

Hand Position: Unknown

Foot Position: Unknown

Restraint Usage: Lap and shoulder belt used

Injuries and Injury Mechanisms

Case vehicle (2000 Mercury Sable)

<u>INJURY</u> <u>OIC CODE</u> <u>ICD-9</u> <u>SOURCE</u>

Driver: Not injured

RF Occupant: Not injured

Vehicle 2

INJURY OIC CODE ICD-9 SOURCE

Driver: Not injured

Occupant Kinematics

The 40-year-old male driver of the case vehicle was seated in a normal, upright position. The seat was adjusted to between the middle and rear most track position. He was wearing the available lap and shoulder belt. The shoulder belt upper anchorage was adjusted to the full down position. The tilt steering wheel was in the middle position. The driver responded to the -70 degree direction of force by moving laterally to the left. He likely engaged the driver's door, but there were no resulting contacts nor any reported injuries.



Figure 10. Contact to center console

The 20-year-old female front right occupant of the case vehicle was seated in what was presumed to be a

normal, upright position. The seat was adjusted to the rear most track position. She was wearing the available lap and shoulder belt. The shoulder belt upper anchorage was adjusted to the full up position.

This occupant responded to the -70 degree direction of force by moving laterally to the left. She likely engaged the center console with her leg-causing it to be displaced to the left. There were, however, no reported injuries to this occupant.

Attachment 1.

