

Remote, Redesigned Air Bag Special Study
FOR NHTSA'S INTERNAL USE ONLY
Dynamic Science, Inc., Case Number (1999-073-027J)
1999 Dodge Dakota
Indiana
April/1999

Technical Report Documentation Page

1. Report No. 1999-073-027J	2. Government Accession No.	3. Recipient Catalog No.
4. Title and Subtitle		5. Report Date March 20, 2000
		6. Performing Organization Report No.
7. Author(s) Dynamic Science, Inc.		8. Performing Organization Report No.
9. Performing Organization name and Address Dynamic Science, Inc. 530 College Parkway, Ste. K Annapolis, MD 21401		10. Work Unit No. (TRAIS) DTNH22-94-D-27058
12. Sponsoring Agency Name and Address U.S. Dept. of Transportation (NRD-32) National Highway Traffic Safety Administration 400 7th Street, SW Washington, DC 20590		13. Type of report and period Covered [Report Month, Year] 14. Sponsoring Agency Code
15. Supplemental Notes		
16. Abstract This remote investigation focused on the redesigned air bag system deployment of a 1999 Dodge Dakota compact pickup truck. This serious injury crash occurred in April, 1999 in the early morning. The weather was clear and the bituminous roadway was dry. The crash occurred on a two-way, divided, interstate highway. The roadway is comprised of seven travel lanes; three eastbound lanes, one eastbound deceleration lane, and three westbound lanes. Eastbound traffic is separated from westbound traffic by a raised concrete "jersey" barrier. The speed limit for this road is 89 kmph (55 mph). There are no traffic controls at the area of impact. The road is level at this location. Vehicle 1, a 1999 Dodge Dakota compact pickup truck (case vehicle) driven by an unrestrained 20 year old male (175 cm/69 in, 79 kg/175 lbs), was traveling east in the right eastbound lane (next to the deceleration lane) at a police estimated speed of 161 kmph (100 mph) approaching the exit ramp. The front right seat was occupied by an unrestrained 18 year old male (185 cm/73 in, 79 kg/175 lbs). The back left seat was occupied by an unrestrained 17 year old male (185 cm/73 in, 91 kg/200 lbs). The back right seat was occupied by an unrestrained 17 year old female (160 cm/63 in, 54 kg/120 lbs). Vehicle 1 was in the process of being pursued by a police cruiser with emergency lights and sirens activated. It is believed that the driver was attempting to enter the exit ramp at the time of the crash. As the driver attempted to exit the highway at a very high rate of speed, he lost control of the vehicle. Vehicle 1 departed the right roadside. Vehicle 1 continued eastbound down the grassy roadside and struck a large steel light support pole with the front plane (12FREE8). Vehicle 1 rotated clockwise after impact and came to final rest to the east of the pole facing southwest. No Delta V was calculated for this crash. As a result of this frontal impact, the supplemental restraint system (driver's and passenger's frontal redesigned air bags) of the case vehicle deployed. The driver was reportedly uninjured in the crash and was not transported from the scene for medical attention. All three passengers sustained varying degrees of injuries and were transported from the scene to a trauma center for medical treatment. The front right occupant was hospitalized, while the back seat occupants were treated and released. Vehicle 1 was disabled in the crash and was towed from the scene with heavy damage.		
17. Key Words Redesigned air bag system, serious injuries		18. Distribution Statement
19. Security Classif. (of this report)	20. Security Classif. (of this page)	21. No of pages
		22. Price

Remote, Redesigned Air Bag Special Study
FOR NHTSA'S INTERNAL USE ONLY
Dynamic Science, Inc., Case Number (1999-073-027J)
1999 Dodge Dakota
Indiana
April/1999

Summary

This remote investigation focused on the redesigned air bag system deployment of a 1999 Dodge Dakota compact pickup truck. This serious injury crash occurred in April, 1999 in the early morning. The weather was clear and the bituminous roadway was dry. The crash occurred on a two-way, divided, interstate highway. The roadway is comprised of seven travel lanes; three eastbound lanes, one eastbound deceleration lane, and three westbound lanes. Eastbound traffic is separated from westbound traffic by a raised concrete "jersey" barrier. The speed limit for this road is 89 kmph (55 mph). There are no traffic controls at the area of impact. The road is level at this location.

Vehicle 1, a 1999 Dodge Dakota compact pickup truck (case vehicle) driven by an unrestrained 20 year old male (175 cm/69 in, 79 kg/175 lbs), was traveling east in the right eastbound lane (next to the deceleration lane) at a police estimated speed of 161 kmph (100 mph) approaching the exit ramp. The front right seat was occupied by an unrestrained 18 year old male (185 cm/73 in, 79 kg/175 lbs). The back left seat was occupied by an unrestrained 17 year old male (185 cm/73 in, 91 kg/200 lbs). The back right seat was occupied by an unrestrained 17 year old female (160 cm/63 in, 54 kg/120 lbs).

Vehicle 1 was in the process of being pursued by a police cruiser with emergency lights and sirens activated. It is believed that the driver was attempting to enter the exit ramp at the time of the crash.



Figure 1. Exterior, Vehicle 1 (1999 Dodge Dakota)



Figure 2. Crash scene. Vehicle 1 approach path.

Crash Events

As the driver attempted to exit the highway at a very high rate of speed, he lost control of the vehicle. Vehicle 1 departed the right roadside. Vehicle 1 continued eastbound down the grassy roadside and struck a large steel light support pole with the front plane (12FREE8). Vehicle 1 rotated clockwise after impact and came to final rest to the east of the pole facing southwest.

No Delta V was calculated for this crash. As a result of this frontal impact, the supplemental restraint system (driver's and passenger's frontal redesigned air bags) of the case vehicle deployed.

The driver was reportedly uninjured in the crash and was not transported from the scene for medical attention. All three passengers sustained varying degrees of injuries and were transported from the scene to a trauma center for medical treatment. The front right occupant was hospitalized, while the back seat occupants were treated and released.

Vehicle 1 was disabled in the crash and was towed from the scene with heavy damage.

Table 1. Delta V

	Case Vehicle	
	km/h	mph
Total	Unknown	Unknown
Longitudinal	Unknown	Unknown
Lateral	Unknown	Unknown



Figure 3. Crash scene. Vehicle 1 point of impact.

Exterior of Case Vehicle

Table 2. Vehicle Information

Model year, make and model	1999 Dodge Dakota
VIN	1B7GL22X1XS
CDC	12FREE8



Figure 4. Exterior, Vehicle 1 (1999 Dodge Dakota pickup)



Figure 5. Exterior, Vehicle 1 (1999 Dodge Dakota pickup)

Table 3. Crush Measurements

Plane of Impact	Field L cm/in.	C1 cm/in.	C2 cm/in.	C3 cm/in.	C4 cm/in.	C5 cm/in.	C6 cm/in.
Bumper	131	0	0	8	16	23	65
	51.6	0	0	3.1	6.3	9.1	25.6

Interior of Case Vehicle

The interior of the Dodge Dakota sustained substantial damage from intrusion and occupant contact. There was major intrusion to the front right side of the vehicle's interior. The intruded values are reported in Table 4. Occupant contact evidence was present to the sunvisor, glove compartment door, seat back, both air bags, and the passenger's air bag cover flap.

The case vehicle was equipped with split bench seats with folding backs with no head restraints in the front left, front center, and front right seating positions. All front seats were adjusted to the middle track position. The front left and front right seats were equipped with integral head restraints. The rear of the vehicle was equipped with bench seats with no head restraints in all three seating positions. The back seats were not adjustable.

Table 4. Intrusions

Intruded Component	Location of Intrusion	Intruded Value cm/in.		Dominant Crush Direction
Side panel	Front right	54	21.3	Longitudinal
Seat cushion	Front right	54	21.3	Longitudinal
Toe pan	Front right	52	20.5	Longitudinal
Right instrument panel	Front right	37	14.6	Longitudinal
Toe pan	Front center	36	14.2	Longitudinal
A-pillar	Front right	25	9.8	Longitudinal
Center instrument panel	Front center	22	8.7	Longitudinal
Windshield header	Front right	5	2	Longitudinal
Windshield	Front right	5	2	Longitudinal
Windshield header	Front center	3	1.2	Longitudinal

Case Vehicle Occupant Protection Systems

The Dodge Dakota compact pickup truck was equipped with a redesigned air bag system which consisted of front left and front right air bag modules which housed air bags and depowered inflator units.

The front left air bag was housed in the steering wheel hub and was concealed by asymmetrical H-configuration cover flaps which were not damaged in the crash. The circular air bag was equipped with two tether straps and no vent ports. Contact evidence consisting of “orange faint stains” was found primarily on the top half of the front of the bag. The air bag was not damaged.

The front right air bag was housed in the mid-instrument panel position and was housed by a single inverted D-shaped cover flap which was not damaged in the crash. The rectangular air bag was not equipped with tether straps or vent ports. Contact evidence consisting of blood was found on the top half of the front and back of the bag. Blood was also bound on the cover flap. The air bag was not damaged.

**Figure 6.** Driver's frontal air bag.

Case Vehicle Occupant Demographics

Table 5. Case Vehicle Occupant(s) Demographics

	Occupant 1		Occupant 2		Occupant 3		Occupant 4	
Age/Sex:	20/Male		18/Male		17/Male		17/Female	
Seated Position:	Front left		Front right		Back left		Back right	
Seat Type:	Bench with folding back - cloth covered		Bench with folding back - cloth covered		Bench - cloth covered		Bench - cloth covered	
Height (cm/in):	175	69	185	73	185	73	160	63
Weight (kg/lbs):	79	175	79	175	97	200	54	120
Pre-existing Medical Condition:	None noted		None noted		None noted		None noted	
Body Posture:	Unknown		Unknown		Unknown		Unknown	
Hand Position:	Unknown		Unknown		Unknown		Unknown	
Foot Position:	Unknown		Unknown		Unknown		Unknown	
Restraint Usage:	None used		None used		None used		None used	
Air bag:	Deployed redesigned air bag system		Deployed redesigned air bag system		None available		None available	

Occupant Injuries

Table 6. Case Vehicle Occupant(s) Injuries

Occupant #	Injury	Injury Severity (AIS)	Injury Mechanism
1	Not injured		
2	Abdomen skin contusion	1	Passenger's frontal air bag
2	Lower left extremity skin contusion	1	Glove compartment door
2	Lower right extremity skin contusion	1	Toe pan
2	Upper right extremity skin abrasion	1	Passenger's frontal air bag
2	Minor facial skin laceration	1	Passenger's frontal air bag
2	Facial skin abrasion	1	Passenger's frontal air bag
2	Nose fracture	2	Passenger's frontal air bag
2	Left humerus fracture	3	Passenger's frontal air bag
2	Left shoulder dislocation	2	Passenger's frontal air bag
2	Right tibia fracture	2	Toe pan
2	Left femur shaft fracture	3	Glove compartment door
2	Lumbar spine compression fracture	2	Passenger's frontal air bag
3	Multiple skin contusions (unknown locations)	1	Unknown source
4	Injured, details unknown		

Occupant Kinematics

The driver of the Dodge Dakota was seated in an unknown posture in the front left position of the vehicle. The other three passengers were also seated in unknown postures in the front right, back left, and back right positions of the vehicle. None of the occupants in Vehicle 1 were restrained. The lack of seat belt usage was determined through visual inspection by the researcher, observations by the investigating police officer at the scene of the crash, and the presence of heavy frontal contact evidence in the vehicle. Prior to impact, the driver applied the brakes (with lock-up) in an attempt to avoid the crash so the occupants may have been out of position.

At impact, the occupants reacted to the 0 degree principle direction of force by moving forward. The driver appears to have contacted the deploying driver's frontal air bag but was not injured in the crash. The front right passenger impacted the deploying passenger's frontal air bag with substantial force-resulting in the lumbar spine fracture, left shoulder dislocation, left humerus fracture, nose fracture, abdominal contusion, right extremity abrasion, facial abrasion, and facial laceration. The passenger's lower extremities contacted the intruding instrument panel and toe pan-causing the right tibia fracture, left femur fracture, and lower extremity contusions. The back left occupant sustained multiple unknown skin contusions from an unknown source. The back right occupant's injuries are not known. The driver was immediately taken into custody by police and was not transported to a hospital from the scene. All three other occupants were transported from the scene to a trauma center for medical attention. The front right passenger was hospitalized for 22 days. The back left and back right passengers were treated and released.



Figure 7. Passenger's air bag contact evidence.

Scene Diagram

