On-scene Investigation / Vehicle to Vehicle Dynamic Science, Inc. / Case Number: DS99014 1998 Oldsmobile Intrigue California January, 1999 This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points be coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the precrash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

**Technical Report Documentation Page** 

		reennea repert Decamentation rage
1. Report No.	2. Government Accession No.	3. Recipient Catalog No.
DS99014		
4. Title and Subtitle		5. Report Date
In-Depth Accident Invest	tigation	February 9, 2000
		6. Performing Organization Report No.
7. Author(s)		8. Performing Organization Report No.
Dynamic Science, Inc.		
9. Performing Organization name and Addre	ss	10. Work Unit No. (TRAIS)
Dynamic Science, Inc.		
530 College Parkway, S	te. K	11. Contract or Grant no.
Annapolis, MD 21401		DTNH22-94-D-27058
12. Sponsoring Agency Name and Address		13. Type of report and period Covered
U.S. Dept. of Transporta	ation (NRD-32)	[Report Month, Year]
National Highway Traffic	c Safety Administration	14. Sponsoring Agency Code
400 7th Street, SW		14. Sponsolning Agency Code
Washington, DC 20590	)	
15. Supplemental Notes		
16. Abstract		
in., 73 kg/162 lbs. The case ve	v, 1999. Vehicle 1, a 1998 Oldsmobile Intrigue, was being dr whicle was equipped with Oldsmobile's standard "Next Gener ental fleet. The front right seat was occupied by a restrained ts in the rear seat.	ration Dual Frontal Air Bags", introduced in the 1998 model
a single High Occupancy Vehic was light and the weather was apparently deployed without ar bag. The front right occupant of	southbound on a multi-lane divided interstate roadway. The cle (HOV) lane. Vehicle 1 was in the lane adjacent to the HC fair. At some point before moving into the HOV lane, both n accompanying crash event. The driver reported that he su did not report any injuries, but did complain of pain in his ear The event was not investigated by any police agency.	DV lane and was preparing to move into that lane. Traffic the driver's side and passenger side frontal air bags ustained a contusion to the left arm from the deploying air

An in-depth inspection of the vehicle exterior–and in particular the undercarriage–was conducted. While there are several minor scrapes to the undercarriage, there is no indication of any impact-related damage which may have caused the deployments. A GM representative attached the diagnostic tool and downloaded the data from the System Diagnostic Module (SDM). Three copies of the data were printed out. On August 3, 1999, the GM representative reported on the interpretation of the codes. The bottom line is that the engineers do not know why the air bags deployed inadvertently. There was no indication of an above-threshold event. The highest delta v recorded was 2.7 km/h (1.7 mph). They report the deployment as essentially a mystery.

17. Key Words		18. Distribution Statement	
Air bag, inadvertent deploy	yment, injury		
19. Security Classif. (of this report)	20. Security Classif. (of this page)	21. No of pages	22. Price

Form DOT F 1700.7 (8\_72) Reproduction of this form and completed page is authorized

# Dynamic Science, Inc. Accident Investigation Case Number: DS99014

# TABLE OF CONTENTS

Background
Description
Investigation Type 1
Crash Location1
Crash Date1
Notification Date 1
Field Work Completed 1
Summary
Scene Diagram
Detailed Information
Vehicles
Occupants
Injuries and Injury Mechanisms
Occupant Kinematics 9

## **BACKGROUND:**

Description:	This case was initiated in response to a report of an inadvertent air bag deployment. This case is being conducted as an on-scene investigation. NHTSA was notified by the driver of the case vehicle.
Investigation Type:	On-scene
Crash Location: Crash Date: Notification Date: Field Work Completed:	California January 1999 January 29, 1999. February 17, 1999

### SUMMARY:

This event occurred in January, 1999. Vehicle 1, a 1998 Oldsmobile Intrigue, was being driven by a properly restrained 41-year-old male (178 cm/70 in., 73 kg/162 lbs). The case vehicle was equipped with Oldsmobile's standard "Next Generation Dual Frontal Air Bags", introduced in the 1998 model year. The vehicle is part of a rental fleet. The front right seat was occupied by a restrained 6-year-old male (122 cm/48 in., 24 kg/52 lbs). There were three additional occupants in the rear seat.

The case vehicle was driving southbound on a multi-lane divided interstate roadway. The roadway at this point is comprised of six travel lanes and a single High Occupancy Vehicle (HOV) lane. Vehicle 1 was in the lane adjacent to the HOV lane and was preparing to move into that lane. Traffic was light and the weather was fair. At some point before moving into the HOV lane, both the driver's and passenger's frontal air bags apparently deployed without an accompanying crash event.



Figure 1. General travel path.

The driver reported that he sustained a contusion to the left arm from the deploying

air bag. The front right occupant did not report any injuries, but did complain of pain in his ears. All occupants also complained of sore throats, presumably from the smoke.

The event was not investigated by any police agency.

The case vehicle was located and inspected it on February 17, 1999. Prior to the inspection, the vehicle had been towed from the scene of the deployment event by the rental company. Shortly after its arrival, it was taken to a local dealership, but prior to any repair work being done it was returned back to the rental agency. Since that time it was held in secure storage by the



Figure 2. Exterior, Vehicle 1

rental company. A legal hold was placed on the vehicle by the driver's attorney for several months. This hold has been removed.

An in-depth inspection of the vehicle exterior–and in particular the undercarriage–was conducted. While there are several minor scrapes to the undercarriage, there is no indication of any impactrelated damage which may have caused the deployments.

A GM representative attached the diagnostic tool and downloaded the data from the SDM<sup>1</sup>. Three copies of the data were printed out. On August 3, 1999, the GM representative reported on the interpretation of the codes. The bottom line is that the engineers do not know why the air bags deployed inadvertently. There was no indication of an above-threshold event. The highest delta v recorded was 2.7 km/h (1.7 mph). They report the deployment as essentially a mystery.



Figure 3. Driver air bag.

<sup>&</sup>lt;sup>1</sup>See Attachment 1

During the interior inspection, it was determined that there was a problem with the passenger side frontal air bag. The air bag had not fully deployed. Some mechanism had restricted the air bag's movement. The air bag was unfurled in a step by step fashion. Further investigation revealed that the air bag (in the area near the middle and right side seams) had been heat-fused to a piece of plastic that is approximately  $2.5 \times 15.2 \text{ cm} (1 \times 6 \text{ in.})$ . The air bag had melted and burned in this area. The piece of plastic has several rivets in it. Its origin or purpose is not known.

The module was not removed at the time of the inspection since this investigator had assured the driver's attorney that no components would be removed.



**Figure 4**. Interior, Vehicle 1. Shows passenger side air bag as found during inspection.




Figure 5. Passenger side air bag.



**Figure 6**. Passenger air bag. Shows exterior of air bag first, then the melted pieces of plastic found on the inside.

## Scene Diagram



# **DETAILED INFORMATION**

## Vehicles

1998 Oldsmobile Intrigue 4 door sedan	
1G3WH52K0WFXXXX	XXX
27,444 km (17,053 miles	)
3.8 L V6	
None reported	
None	
Minor scrapes to the undercarriage, but there was no indication of any impact-related damage which may have caused the deployments	
NA	
Total	NA
Longitudinal	NA
Latitudinal	NA
Energy	NA
	1G3WH52K0WFXXXX 27,444 km (17,053 miles 3.8 L V6 None reported None Minor scrapes to the under no indication of any impara may have caused the depl NA Total Longitudinal Latitudinal

# Occupants

Vehicle 1	Occupant 1	Occupant 2
Age/Sex:	41/Male	6/Male
Seated Position:	Front left	Front right
Seat Type:	Bucket	Bucket
Height:	178 cm (70 in.)	122 cm (48 in.)
Weight:	73 kg (162 lbs.)	24 kg (52 lbs.)
Occupation:	Unknown	NA
Pre-existing Medical Condition:	None noted	None noted
Alcohol/Drug Involvement:	None	NA
Driving Experience:	Unknown	NA
Body Posture:	Normal, upright	Normal, upright
Hand Position:	Both hands on wheel	Unknown
Foot Position:	Right foot on accelerator, left on floor	Unknown
Restraint Usage:	Lap and shoulder belt used <sup>2</sup>	Lap and shoulder belt used
Air bag:	Deployed	Partially deployed

<sup>&</sup>lt;sup>2</sup>Verified by SDM printout

Vehicle 1			
Age/Sex:	36/Female	Unk/Male child	8/Female
Seated Position:	Unknown, rear seat	Unknown, rear seat	Unknown, rear seat
Seat Type:	Bench	Bench	Bench
Height:	Unknown	Unknown	Unknown
Weight:	Unknown	Unknown	Unknown
Occupation:	Unknown	Unknown	
Pre-existing Medical Condition:	None noted	None noted	None noted
Alcohol/Drug Involvement:	NA	NA	NA
Driving Experience:	NA	NA	NA
Body Posture:	Unknown	Unknown	Unknown
Hand Position:	Unknown	Unknown	Unknown
Foot Position:	Unknown	Unknown	Unknown
Restraint Usage:	Unknown	Unknown	Unknown
Air bag:	None available	None available	None available

### **Injuries and Injury Mechanisms**

Vehicle 1

	INJURY	OIC CODE	<u>ICD-9</u>	<u>SOURCE</u>
Driver:	Contusion, left arm	790402.1,2	923.10	Air bag
RF Occupant:	Not injured			
Occupant (03):	Not injured			
Occupant (04):	Not injured			
Occupant (05):	Not injured			

### **Occupant Kinematics**

The driver of Vehicle 1 was seated in a normal, upright position. Both hands were on the steering wheel. His right foot was on the accelerator, his left on the floor. He was wearing the available lap and shoulder belt. The D-ring was in the full up position. There was 55 cm longitudinally between the face of the steering wheel module and the front of the front seat. There was no known precipitating event which caused the deployment so the driver was still in his normal, relaxed position as the air bag deployed. As the air bag deployed, it contacted the inner part of the driver's left arm–causing a contusion. He was not aware if his hand ever came off the steering wheel.

Insofar as the other occupants are concerned, there were no related kinematics nor any air bag contact. The air bag for the passenger side did not deploy to any degree where it might have come into contact with the belted occupant.

# Attachment 1. SDM printout

SIR SIR EEPRON DATA		1
Write in DATE: 2/17/99 DB		
Write in VIN: 16.7WH 52KOWF		
RDM identification: 88		
8686: 18 48 44 90 84 88 88 88		
8486: AA 88 80 00 00 00 80 88		
B610: AA 00 00 00 20 07 F9 F9		
8618: F9 F9 F9 F9 F9 80 FF 88		
8620: AA AA 88 88 88 88 88 70 8628: 88 88 48 89 88 87 87 87		
6430: 07 06 07 07 07 06 07 07 07		
8638: 06 86 06 06 06 06 05 85		
8640: 05 05 05 05 05 05 05 05	TECH 1 DATA LIST	
3648: 05 05 06 C8 0F 00 08 FF		
6650: 00 55 55 55 AA AA 01 00	1. PSIR1 LOW	
8658: 00 68 00 00 00 00 00 80 80	2. F51K2 LON	
8668: 00 00 00 00 00 00 00 00	3. PASS SUPP DEF DISABLED	
8668: 28 88 88 80 00 00 08 88 8470: 88 88 89 82 88 88 89	4. DPSIR DFF S. IGNITION 11.8 V	
	6. 0005T 11.8 V	
	6. ACCSI - 1 6 7. DRIV. SENSELO 0.1 V	
8688: 20 00 82 A3 96 00 02 A4	8. PASS. SENSELO 0.2 V	
8690: 97 08 02 AH 98 80 00 08	9. DRESF 22.7 V 10. PRESF 23.0 V	
BASNE     DD     DD <thd< th=""><th>10. PRESE 23.0 V</th><th></th></thd<>	10. PRESE 23.0 V	
B6A0: 93 00 02 94 94 88 02 A1	11. DRIVER VDIF 0.476 V 12. PASS. VDIF 0.007 V 13. DRIVER RESIST. 8.6 DHNS 14. DRIVER RESIST. 8.6 DHNS	
8648= 95 80 88 88 88 88 88 80 80 8688= 98 88 88 88 88 88 88 88	12. PASS. VDIF 0.007 V	
8468: 38 38 38 38 88 88 88 72 6E C6	16 DRIVER RESIST. B. B BHAS	
B6C0: 34 4E 1A 01 00 64 02 AA	14. PASS. RESIST, 0.0 OHMS 15. RAM DOWNLOAD DISABLED	
86C8: 00 AA 00 00 00 00 01 01	16. CLEAR CRASH DATA DISABLED	
BEDO: BE CE CC C7 BE B1 BE AC	17. DSBF0 ACTIVE 10. DRIVER SEATBELT BUCKLED	
B6D3; 68 EE B4 87 ED B0 88 00	18. DRIVER SEATBELT BUCKLED	
86E0: 00 00 FF FF 00 00 02 57	19. LAMPFB# ACTIVE 20. LAMP DRIVER INTERNAL	
9628: 12 00 00 00 00 00 00 00 86F0: 28 08 F0 05 50 86 00 23	20. LHAP DRIVER INTERNAL 21. LODATED LABO DE ON D.	
36781 64 FF FF FF FF FF FF FF	21. WARNING LAMP ON ON 2.8 HOURS   22. WARNING LAMP ON 2.8 HOURS   23. ADS STATUS NDT EXPECTED   24. LPS STATUS NOT EXPECTED	
8700: 52 52 52 53 5A 50 5D 7F	23. ADS STATUS NOT EXPECTED	
8708: 84 86 87 86 8F 94 96 60	24. LPS STATUS NOT EXPECTED	
DITES HI HE BO BH BF LI DI DH	25. HSUI OVERLAP	
3718: E2 ED F8 41 43 46 48 48	26. SINK 180 SINK OFF	
8720: 40 40 51 53 56 58 5A 50 8728: 50 60 62 64 65 66 68 69	27. AUXINEB	-
8738: 68 6C 6D 6E 6F 78 71 72	28. SFAULT ADS/LPS FAUL 29. DSLF INACTIVE	2. 19
8738: 72 73 74 74 75 75 75 76	30. PSLF INACTIVE	
8748: 76 76 77 77 77 77 77 77	31. TXEN ACTIVE	
8748: 77 77 77 77 77 77 77 77 77	32. TEST INACTIVE	
6750: 77 77 77 77 77 77 77 9755: 77 77 77 77 90 10 90	33. D/P PASS SIDE	
9758: 77 77 77 77 77 00 18 00 8760: 28 14 28 50 20 18 00 00	34. SYSTEM TYPE D/P SYSTEM 35. TXD ACTIVE	
8768; 20 AA 80 50 51 FF FF FF	35. TXD ACTIVE 36. RXD INACTIVE	
8770: FF FF FF FF 4A 4A 4A 4A	37. WARN CONMAND ON	
8778: 4F 51 51 51 51 51 51 51	38. RMEAS 2 MA ON	
8780: 51 54 54 57 59 50 5F 61	39. FETEN INACTIVE	
8788: 63 63 65 65 65 65 65 65 8790: 65 65 65 65 65 65 65 65	40. TEST INACTIVE	
87782 65 65 65 65 65 65 65 65	41. RDM ID \$85 42. SDM ID \$50	
87A8: 65 65 65 65 65 65 65 65	43. PLATFORN IO W CRR	
8748: 45 65 65 65 65 65 65 65	44. CAL ID \$12	
8788: 65 65 65 65 65 65 65 65	45. ENRD# ENABLED	
8788: 45 65 65 65 65 68 00 00	46. CLOCK OFF	
8708: 00 00 81 41 00 20 00 00 00 8708: 00 00 20 00 00 00 00 00		
87D2: 00 00 00 00 00 00 00 00		
THE ST OF OF OF OF OF OF OF	AN TANK LANG DA DR. DATE DATE A TANK MADE	