



WORLD HEADQUARTERS • LAW DEPARTMENT

02E-017

RECEIVED

2002 MAR -6 A 9:48

OFFICE OF
DEFECTS INVESTIGATION

February 8, 2002

Donald W. Commons
Direct No.: (419) 535-4664
E-Mail: don.commonson@dana.com

Kenneth N. Weinstein, Esq.
Associate Administrator for Safety Assurance
National Highway Traffic Safety Administration
400 Seventh Street, S.W., Room 5321
Washington, D.C. 20590

Re: 00E-047.004; Third Supplemental Submission

Dear Mr. Weinstein:

Dana Corporation (Dana) is further supplementing its Part 573 notice letter in the above-captioned matter. The Part 573 letter was submitted on September 12, 2000; initial and second supplemental letters were transmitted to the agency on September 22, 2000, and October 4, 2000, respectively.

The only changes which Dana is reporting here relate to extension of the safety campaign to include E-1320-I axle applications (13,200 lb. axles) on Kenworth and Freightliner heavy vehicles. The additional axle assemblies involved in the campaign extension, numbering 5,306, were manufactured by Dana's Spicer Heavy Axle Division during the period June 17, 1999 through July 31, 2000.

Included with this letter is a revised Attachment A, listing the additional axle assemblies included in the safety campaign. With the additional units, the total axle assembly population in the campaign is amended to 12,311 units.

As Dana previously advised NHTSA, TRW is underwriting the product, labor and handling costs involved in this safety campaign. This includes all reported extensions of the campaign, including the portion covered by this letter.

Sincerely,

Donald W. Commons
Senior Counsel

Enclosure (Revised Attachment A)

People Finding A Better Way

Customer	Axle Assembly Number	Cross Link Number	Steer Axle Model	Expanded Ship Dates	Expanded Quantity	Original Ship Dates	Original Quantity
Kenworth	316110	815327	1200I	6/23 - 11/24/1999 5/17 - 7/29/2000	191	7/22 - 9/23/1999	46
Kenworth	316695	815327	1200I	6/15 - 10/16/1999 5/24 - 7/31/2000	75	7/7 - 10/16/1999	36
Kenworth 1200I Sub Total				266			82
Mack	317824	815327	1200I	6/17 - 11/16/1999 5/17 - 7/17/2000	71	7/13 - 10/16/1999	15
Mack	317825	815327	1200I	6/17 - 11/30/1999 5/17 - 7/21/2000	1415	7/7 - 10/30/1999	466
Mack	317826	815327	1200I	6/21 - 11/19/1999 5/17 - 7/21/2000	313	7/7 - 10/27/1999	142
Mack	317808	815327	1200I	6/17 - 11/30/1999 5/17 - 7/21/2000	2281	7/7 - 10/30/1999	904
Mack	825487	815327	1200I	6/21 - 11/13/1999 5/17 - 7/21/2000	381	7/8 - 10/30/1999	224
Mack	825486	815327	1200I	6/17 - 11/30/1999 5/17 - 7/21/2000	1959	7/7 - 10/30/1999	626
Mack 1200I Sub Total				6420			2377
Kenworth	315575	970578	1320I	6/26 - 11/19/1999 5/18 - 6/12/2000	40	7/7 - 10/21/1999	25
Kenworth	315576	970578	1320I	6/17 - 11/29/1999 5/16 - 7/29/2000	376	7/7 - 10/30/1999	188
Kenworth	315577	970578	1320I	6/17 - 11/29/1999 5/16 - 7/31/2000	4890	7/7 - 10/30/1999	3048
Kenworth 1320I Sub Total				5306			3261
Freightliner	315651	970578	1320I	6/28 - 11/19/1999 4/26 - 7/25/2000	183	7/23 - 9/21/1999	105
Freightliner	318293	970578	1320I	8/3 - 12/27/1999 4/29 - 7/22/2000	66	8/3 - 10/28/1999	22
Freightliner	318294	970578	1320I	6/28 - 11/23/1999 6/18 - 8/17/1999	24	8/10 - 10/22/1999	17
Freightliner	325032	970578	1320I	6/18 - 8/17/1999 6/29/2000	22	8/10 - 8/17/1999	4
Freightliner	326440			11/17 - 12/20/99	3		
Freightliner	315650	970578	1320I	7/22/2000	10		
Freightliner	325199	970578	1320I	7/27/1999	1	07/07/1999	1
Freightliner	325444	970578	1320I	08/17/1999	1	08/17/1999	1
Freightliner	326661	970578	1320I	12/20/1999	1		
Freightliner 1320I Sub Total				311			150
PACCAR	970580		Verticle Socket	7/7 - 8/27/99	4	7/7 - 8/27/1999	4
PACCAR	326839			05/24/2000	4		
Paccar Sub Total				8			4
				12311			5874

Freightliner Dates are Expansion
above TRW's per Freightliner's request

11/05/2001

TRW 20-EDL Ball Socket Recall

Recall Number	Manufacturer	573 Date	Affected Component	Number Defective	Amendment
00E-047	TRW	08/25/00	Tie Rod	74,929	
	TRW	08/25/00	Drag Link	34,457	
	TRW	08/25/00	Ball Socket (AM) ¹	86,556	
	Dana	09/12/00	Tie Rod	6,686	
	ArvinMeritor	10/02/00	Tie Rod	53,000	
	Westport	10/20/00	Tie Rod	143	
	TRW	06/08/01	Tie Rod	109,929	Yes
	TRW	06/08/01	Ball Socket (AM) ¹	126,556	Yes
	ArvinMeritor	06/27/01	Tie Rod	93,000	Yes
	ArvinMeritor	06/27/01	Ball Socket (AM) ¹	19,000	Yes
02E-017	Dana	02/08/02	Tie Rod	5,306	Yes
	ArvinMeritor	04/02/02	Tie Rod	119,000	Yes
	ArvinMeritor	04/02/02	Tie Rod (AM)	62,000	Yes
00V-246	Freightliner	08/23/00	Tie Rod	45,000	
	PACCAR	08/30/00	Tie Rod	3,260	
	Mack	12/13/00	Tie Rod	6,244	
	International	10/11/00	Tie Rod	8,760	
	International	10/11/00	Drag Link	15,257	
	Volvo	10/16/00	Tie Rod	6,575	
	Volvo	10/16/00	Ball Socket	730	
	E-One	10/30/00	Tie Rod	3	
	Ford	11/20/00	Tie Rod	17,700	
	Spartan	09/12/00	Drag Link	860	
	Western Star	09/27/00	Tie Rod	303	
	Athey	11/02/00	Ball Socket	17	

¹ (AM) - Aftermarket

Recall Number	Manufacturer	573 Date	Affected Component	Number Defective	Amendment
01V-139	Volvo	11/08/00	Tie Rod	13,373	Yes (00V-246)
	Athey	04/25/01	Tie Rod	251	Yes (00V-246)
01V-140	MCI	12/23/00	Tie Rod	596	
	Freightliner	09/13/01	Tie Rod	75,000	Yes (00V-246)
	PACCAR	08/24/01	Tie Rod	2,294	Yes (00V-246)
	Mack	09/19/01	Tie Rod	8,794	Yes (00V-246)
	International	07/25/01	Tie Rod	18, 348	Yes (00V-246)
	Isuzu	06/15/01	Tie Rod	203	
	Forest River	04/26/01	Tie Rod	160	
	GM	04/10/01	Tie Rod	6,386	
02V-037	Reliance (trailer)	01/21/02	Tie Rod	15	
	Volvo	10/17/01	Tie Rod	8,573	Yes (01V-139)
	PACCAR	06/10/02	Tie Rod	2,293	Yes (01V-140)