

1200 New Jersey Avenue SE Washington, DC 20590

March 16, 2011

MR. JOHN EUTSEY WARRANTY SIERRA CUSTOM INTERIORS 19224 CR 8 WEST BRISTOL, IN 46507 NVS-215dgl 11V-171

SUBJECT: REFRIGERATORS/POSSIBLE FIRE/NORCOLD

DEAR MR. EUTSEY:

This letter serves to acknowledge Sierra Custom Interiors' notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall campaign which will be conducted pursuant to Federal law for the vehicles listed below.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: SIERRA/FEATHERLITE/2008 SIERRA/CIMARRON/2005 SIERRA/UNITED/2008

NHTSA Campaign Number: 11V-171

Mfg's Report Date: March 8, 2011

Components: EQUIPMENT: RECREATIONAL VEHICLE

Potential Number of Units Affected: 3

Summary:

SIERRA IS RECALLING CERTAIN MODEL YEAR 2005 CIMARRON AND MODEL YEAR 2008 FEATHERLITE AND UNITED TRAILERS EQUIPPED WITH 1200-SERIES NORCOLD REFRIGERATORS. THE POPULATION OF REFRIGERATORS BEING ADDRESSED CONTAINS EITHER A SENSING ALGORITHM OR THERMAL SWITCH TO SHUT OFF POWER TO THE REFRIGERATOR WHEN HIGH TEMPERATURES ARE DETECTED IN ORDER TO PREVENT A POTENTIAL FIRE. THE RESPONSE TIMES OF THE SENSOR ALGORITHM AND THERMAL SWITCH DEVICES TO STOP POWER ARE NOT SUFFICIENT.

Consequence:

THE SENSING ALGORITHM OR THERMAL SWITCH INSTALLED TO SHUT OFF POWER TO THE REFRIGERATOR WHEN HIGH TEMPERATURES ARE DETECTED DUE TO A POSSIBLE HYDROGEN GAS LEAK MAY NOT SHUT OFF IN SUFFICIENT TIME TO PREVENT A FIRE.

Remedy:

SIERRÀ IS WORKING WITH NORCOLD TO IDENTIFY AND NOTIFY ANY AFFECTED OWNERS. OWNERS WILL BE INSTRUCTED TO CONTACT NORCOLD DEALERS TO RECEIVE THE REMEDY FREE OF CHARGE. PLEASE SEE NORCOLD'S DEFECT REPORT 10E-049 FOR ADDITIONAL INFORMATION. THE SAFETY RECALL BEGAN ON FEBRUARY 18, 2011. OWNERS MAY CONTACT NORCOLD AT 1-800-767-9101.

Notes:

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO <u>HTTP://WWW.SAFERCAR.GOV</u>.

It is our understanding that notification to owners began on February 18, 2011, prior to our review of the owner notification letter. In the future, please ensure this office reviews a draft of your proposed owner notification letter at least five business days before you intend to mail those letters. Should it become necessary for Sierra to do a renotification, the follow-up notification must be submitted to this office for review and it must comply with the requirements of Part 577.5, "Notification pursuant to a manufacturer's decision" and Part 577.10, "Follow-up notification."

Please provide the following additional information and be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in your report, Norcold will be handling the remedy, and quarterly reporting for this campaign. However, please be advised that 49 CFR 573.6 provides that the vehicle manufacturer is responsible for any safety related defect or any noncompliance in the vehicle or any item of original equipment. If Norcold's campaign is not satisfactory, you may be required to conduct a follow-up notification.

Your contact for this recall will be Delia Lopez who may be reached by phone at 202-366-9525, or by email at <u>Delia.lopez@dot.gov</u>, or through the office email at <u>RMD.ODI@dot.gov</u>. We look forward to working with you toward a successful completion of this recall campaign.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigation Enforcement