



Mack Trucks, Inc.

Safety Recall ALERT

Date: April 6, 2011 **Number:** SRA-M11-01
To: All U.S. & Canadian Distributors
Attention: Service Manager, Warranty Manager, Parts Manager, Dealer Principal
From: Regulatory Affairs Department
Subject: Safety Recall, SC0349, SC0350, Mirror Switch

Safety Recall Summary:

On certain Mack MRU (SC0350) & LEU (SC0349) model vehicles manufactured from January 3, 2007 through February 3, 2011 with electronically adjustable mirrors the circuit protection does not provide adequate over current protection. As a result, the mirror switch can overheat, which may result in a vehicle fire.

There are approximately (3,872) vehicles (3,763 US; 109 Canada; Export) that may contain the defect.

Dealer's Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act require dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Release Schedule:

- Repair Instructions are tentatively scheduled for release no later than May 23, 2011.
- Vehicle list is tentatively scheduled to be posted on the Trucks Dealer Portal April 8, 2011.
- Owner Notices are scheduled to be mailed on or before May 30, 2011.

Questions:

Contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com if you have questions.