## **DAIMLERCHRYSLER**

## SAFETY RECALL TO INSTALL A SECONDARY SEAL OVER YOUR VEHICLE'S FUEL PUMP MODULE

Dear PT Cruiser Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

DaimlerChrysler Corporation has determined that a defect, which relates to motor vehicle safety, exists in some 2001 and 2002 model year Chrysler PT Cruiser vehicles.

The problem is...

DaimlerChrysler has determined that the fuel pump module mounting flange on your PT Cruiser (identified on the enclosed form) may leak fuel if your vehicle is involved in a rollover collision. Fuel leakage in the presence of an ignition source can result in a fire.

What DaimlerChrysler and your dealer will do...

DaimlerChrysler will make improvements to your vehicle free of charge (parts and labor). To do this, your dealer will install a secondary seal over the fuel pump module. The work will take about ½ hour to complete. However, additional time may be necessary depending on how dealer appointments are scheduled and processed.

What you must do to ensure your safety...

- > Simply **contact your dealer** right away to schedule a service appointment. Ask the dealer to hold the parts for your vehicle or to order them before your appointment.
- > Bring the enclosed form with you to your dealer. It identifies the required service to the dealer.

If you need help...

If you have questions or concerns which the dealer is unable to resolve, please contact the DaimlerChrysler Customer Assistance Center at 1-800-853-1403. A representative will assist you.

If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, DC 20590, or call the toll-free Auto Safety Hotline at 1-888-327-4236.

We're sorry for any inconvenience, but we are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Services Field Operations DaimlerChrysler Corporation

B23

Buckle up for Safety