



September 22, 2011

MR. NASSER ZAMANI SENIOR MANAGER, COMPLIANCE AND REGULATORY AFFAIRS DAIMLER TRUCKS NORTH AMERICA LLC 4747 N. CHANNEL AVENUE PORTLAND OR 97217-3849 NVS-215dgl 11V-478

SUBJECT: DIESEL FUEL LEAK/DETROIT DIESEL

DEAR MR. ZAMANI:

This letter serves to acknowledge Daimler Trucks North Americas LLC's (DTNA) notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall campaign which will be conducted pursuant to Federal law for the vehicles listed below.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FREIGHTLINER/BUSINESS CLASS M2/2004-2008 FREIGHTLINER/CASCADIA/2004-2008 FREIGHTLINER/COLUMBIA/2004-2008 FREIGHTLINER/FLD/2004-2008 STERLING/A-LINE/2004-2008 STERLING/L-LINE/2004-2008 WESTERN STAR/4900/2004-2008

NHTSA Campaign Number: 11V-478

Mfg's Report Date: September 16, 2011

Components: FUEL SYSTEM, DIESEL

Potential Number of Units Affected: 73,500

Summary:

DAIMLER TRUCKS IS RECALLING CERTAIN MODEL YEAR 2004 THROUGH 2008 HEAVY TRUCKS MANUFACTURED FROM JULY 11, 2003, THROUGH SEPTEMBER 28, 2007, EQUIPPED WITH EPA04 MODEL MBE4000 ENGINES BUILT WITH PLASTIC LOW PRESSURE FUEL LINES AND FUEL FILTERS MOUNTED NEAR THE CENTER OF THE ENGINE ON THE LEFT-HAND SIDE. THE PLASTIC LOW PRESSURE FUEL LINE BETWEEN ENGINE MOUNTED FUEL FILTER AND ENGINE BLOCK MAY DEVELOP A SUBSTANTIAL DIESEL FUEL LEAK.

Consequence:

THIS COULD CREATE ROAD HAZARD INCREASING THE RISK OF A CRASH. FUEL LEAKAGE, IN THE PRESENCE OF AN IGNITION SOURCE, COULD RESULT IN A FIRE.

Remedy:

DAIMLER TRUCKS WILL NOTIFY OWNERS AND THE REMEDY WILL BE PERFORMED BY DETROIT DIESEL CORPORATION AUTHORIZED REPAIR FACILITIES. VEHICLES WILL BE INSPECTED AND THE PLASTIC LOW PRESSURE FUEL LINE WILL BE REPLACED WITH A STEEL LOW PRESSURE FUEL LINE. THIS SERVICE WILL BE PERFORMED FREE OF CHARGE. THE MANUFACTURER HAS NOT YET PROVIDED AN OWNER NOTIFICATION SCHEDULE. OWNERS MAY CONTACT DAIMLER TRUCKS AT 1-800-547-0712.

Notes:

DAIMLER TRUCKS' CAMPAIGN NUMBER IS 11C-2. CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO HTTP://WWW.SAFERCAR.GOV.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. The owner notification letter needs to be distributed within 60 days of this acknowledgement. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in your report, Detroit Diesel will be handling the remedy, and quarterly reporting for this campaign. However, please be advised that 49 CFR 573.6 provides that the vehicle manufacturer is responsible for any safety related defect or any noncompliance in the vehicle or any item of original equipment. If Detroit Diesel's campaign is not satisfactory, you may be required to conduct a follow-up notification.

Your contact for this recall will be Delia Lopez who may be reached by phone at 1-202-366-9525, or by email at Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you toward a successful completion of this recall campaign.

Sincerely,

Ric Willard

Acting Chief, Recall Management Division

Office of Defects Investigation

Enforcement