

September 13, 2012

Mr. GLEN PERLMAN SR. VICE PRESIDENT/GENERAL COUNSEL NATIONAL VAN BUILDERS, INC. 800 PINE STREET ATTLEBORO, MA 02703

Subject: Wheelchair Lift/Outer Roll Stop Latching Mechanism

Dear Mr. PERLMAN:

This letter serves to acknowledge NATIONAL VAN BUILDERS, INC.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

NATIONAL VAN/FORD E-150/2006-2011 NATIONAL VAN/FORD E-250/2006-2011 NATIONAL VAN/FORD E-350/2006-2011

Mfr's Report Date: September 4, 2012

NHTSA Campaign Number: 12V-437

Components: EQUIPMENT ADAPTIVE

Potential Number of Units Affected: 605

Problem Description:

National Van Builders, Inc., (National Van Builders) is recalling certain model year 2006-2011 Ford E-150, E-250, and E-350 vehicles equipped with Braun Century-2 and/or Vista-2 wheelchair lifts. Over time and with frequent use, the roll stop latches on the outer barrier may become bent or misaligned.

Consequence:

A wheelchair occupant may defeat or ride over the insufficiently latched roll stop. If this occurs when the lift platform is in an elevated position, the wheelchair's occupant could fall and sustain injury.

Remedy:

National Van Builders will notify owners in September 2012, and the repairs will be performed by authorized Braun dealers free of charge. Owners may contact National Van Builders, Inc., at 1-508-222-2272.

Notes:

Owners may also contact the National Highway Traffic Safety Administration's Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NVS-215ET 12V-437

We have received your proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

It is understood that Braun will be handling the quarterly reporting for this campaign.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Your contact for this recall will be Edison Thompson who may be reached by phone at 202-366-9525, or by email at edison.thompson@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigations Enforcement

