



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

November 19, 2012

Mr. Chris Sandvig
General Manager Compliance/TREAD
Volkswagen of America, Inc.
3800 Hamlin Road
Auburn Hills, MI 48326

NVS-215KS
12V-540

Subject: Occupant Detection System may Fail when Wet

Dear Mr. Sandvig:

This letter serves to acknowledge Volkswagen of America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
VOLKSWAGEN/BEETLE/2012-2013

Mfr's Report Date: November 14, 2012

NHTSA Campaign Number: 12V-540

Components:
AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE

Potential Number of Units Affected: 2,471

Problem Description:

Volkswagen is recalling certain model year 2012-2013 Beetle vehicles, manufactured from February 2012, through August 2012, and equipped with leather sport seats. If the right front passenger seat gets wet, the occupant control module may not properly detect the presence of a child restraint installed in the seat.

Consequence:

If the control module does not detect a child seat installed, the airbag will not turn off. If the airbag does not turn off, in the event of a crash necessitating front airbag deployment, a child secured in the child seat may be at an increased risk for serious injury.

Remedy:

Volkswagen will notify owners, and replace the control modules, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Volkswagen at 1-800-822-8987.

Notes:

Volkswagen's campaign recall number is 69i9/W6. Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to provide an estimated date including month, day, and year, when you will send notifications to owners, dealers, and distributors as soon as it becomes available. Please be reminded that it is expected owners will be notified of a safety defect in their vehicles within 60 days of a manufacturer's notification to NHTSA of a safety defect in those vehicles.

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement