RECEIVED

2002 NAR -6 A 9: 48

Donald W. Commons
Direct No.: (419) 535-4664
E-Mail: don.commons@dana.com

February 8, 2002

DEFECTS INVESTIGATION

Kenneth N. Weinstein, Esq. Associate Administrator for Safety Assurance National Highway Traffic Safety Administration 400 Seventh Street, S.W., Room 5321 Washington, D.C. 20590

Re: 00E-047.004; Third Supplemental Submission

Dear Mr. Weinstein:

Dana Corporation (Dana) is further supplementing its Part 573 notice letter in the above-captioned matter. The Part 573 letter was submitted on September 12, 2000; initial and second supplemental letters were transmitted to the agency on September 22, 2000, and October 4, 2000, respectively.

The only changes which Dana is reporting here relate to extension of the safety campaign to include E-1320-I axle applications (13,200 lb. axles) on Kenworth and Freightliner heavy vehicles. The additional axle assemblies involved in the campaign extension, numbering 5,306, were manufactured by Dana's Spicer Heavy Axle Division during the period June 17, 1999 through July 31, 2000.

Included with this letter is a revised Attachment A, listing the additional axle assemblies included in the safety campaign. With the additional units, the total axle assembly population in the campaign is amended to 12,311 units.

As Dana previously advised NHTSA, TRW is underwriting the product, labor and handling costs involved in this safety campaign. This includes all reported extensions of the campaign, including the portion covered by this letter.

Sincerely,

Donald W. Commons Senior Counsel

Enclosure (Revised Attachment A)

People Finding A Better Way

Number		Axle Assembly	Cross Link	Steer Axle	Expanded	Expanded	Original	Original
316110 815327 12001 673-1474999 191 7122-9/23/1899 180-1474999 191 7122-9/23/1899 180-1474999 191 7122-9/23/1899 180-1474999 191 717-14/18999 191	Customer	Number	Number	Model	Ship Dates	Quantity	Ship Dates	Quantity
316895 815327 12001 6175-10161989 75 777-10161989 75 777-10161989 75 777-10161989 75 777-10161989 775 777-10161989 775 777-10161989 775 777-10161989	Kenworth	316110	815327	12001	6/23 - 11/24/1999 5/17 - 7/28/2000	191	7/22 - 9/23/1999	46
317824 815327 1200 6177-11702000 777 7773-10761999 777-10761999	Kenworth	316695	815327	12001	6/15 - 10/16/1999	75	7/7 - 10/16/1999	36
317824 815327 1200 6/17 - 1/1/6/1999 77 7/13 - 1/0/1999 77 7/13 - 1/0/1999 77 7/13 - 1/0/1999 77 7/13 - 1/0/1999 77 7/13 - 1/0/1999 77 7/13 - 1/0/1999 77 7/13 - 1/0/1999 77 7/13 - 1/0/1999 77 7/13 - 1/0/1999 7/13 - 1/0/				Kengarth 1200 Sub	Total	266		83
317825 815327 1200 617 - 171500 313 777 - 10301999 317808 815327 1200 617 - 171510000 317 - 171510000000000000000000000000000000000	Mack	317824	815327	12001	6/17 - 11/16/1999	71	7/13 - 10/16/1999	15
317826 815327 1200 617-17180199 313 777-10120199 317808 815327 1200 617-17180199 2281 777-101201999 617-171801999 2281 777-101201999 617-171801999 2281 777-101201999 617-171801999 317-771801999 777-101201999	Mack	317825	815327	12001	6/17 - 11/30/1999	1415	7/7 - 10/30/1999	466
317808 815327 12001 6177 - 11730/1999 2281 777 - 10730/1999 825486 815327 12001 6177 - 7121/2000 6420 777 - 10730/1999 825486 815327 12001 6177 - 7121/2000 6420 777 - 10730/1999 870578 13201 6177 - 11736/1999 376 777 - 10730/1999 870578 13201 6177 - 11736/1999 376 777 - 10730/1999 870578 13201 6177 - 11736/1999 376 777 - 10730/1999 777 - 10730/1999 870578 13201 6177 - 11736/1999 4890 777 - 10730/1999 777	Mack	317826	815327	12001	6/21 - 11/19/1999	313	7/7 - 10/27/1999	142
S25487 S15327 1200 6t21 - 11/13/1999 381 7t8 - 10/20/1999 825486 S15327 1200 6t77 - 71/21/2000 6420 7t7 - 10/20/1999 315575 970578 1320 6t78 - 71/23/2000 6t77 - 71/20/2000 6t77 - 71/20/2000 6t77 - 71/20/2000 6t77 - 71/20/1999 375575 970578 1320 6t78 - 71/23/2000 6t78 - 71/23/2000 6t77 - 71/20/1999 376 7t7 - 10/20/1999 7t7 - 10/20	Mack	317808	815327	12001	6/17 - 11/30/1999	2281	7/7 - 10/30/1999	904
S25486 S1537 1200 Git7 - 11301999 1959 717 - 1030/1999 19575 13201 Giv2 - 11/19/1999 40 717 - 10121/1999 1315575 970578 13201 Giv2 - 11/19/1999 4890 717 - 10130/1999 1315577 970578 13201 Giv2 - 11/19/1999 4890 717 - 10130/1999 1315577 970578 13201 Giv2 - 11/19/1999 4890 717 - 10130/1999 1315577 970578 13201 Giv2 - 11/19/1999 13201 Giv2 - 11/19/1999 177 - 10130/1999 13201 Giv2 - 11/19/1999 1475- 12/20/1999 147	Mack	825487	815327	12001	6/21 - 11/13/1999	381	7/8 - 10/30/1999	224
315575 970578	Mack	825486	815327	12001	6/17 - 11/30/1999	1959	7/7 - 10/30/1999	626
315575 970578 1320 678 - 11/19/1999 40 777 - 10/21/1999 40 777 - 10/21/1999 4890 777 - 10/30/1999 4890 777 - 10/30/1999 4890 777 - 10/30/1999 777 - 10/30				Mack 1200! Sub Tet	I	6420		2377
315576 970578 1320 6/17 - 11/29/1999 376 777 - 10/30/1999 315577 970578 1320 6/17 - 11/29/1999 4890 777 - 10/30/1999 7	Kenworth	315575	970578	13201	i	40	7/7 - 10/21/1999	25
315577 970578 1320 6/17 - 1/129/1999 4890 7/7 - 10/30/1999 4890 7/7 - 10/30/1999 4890 7/7 - 10/30/1999 4/75 - 7/31/2000 4/75 - 7/31/2000 4/75 - 7/31/2000 4/75 - 7/31/2000 4/75 - 7/31/2000 4/75 - 7/31/2000 4/75 - 7/31/2000 4/75 - 7/31/2000 4/75 - 7/31/2000 4/75 - 7/21/399 4/75 - 9/70578 4/75 - 9/70578 4/75 - 9/70578 4/75 - 9/70578 4/75 - 9/70578 4/75 - 9/70578 4/75 - 9/70578 4/75 - 9/70579 4/75 - 9/70579 4/75 - 9/705799 4/75 - 9/705799 4/75 - 9/705799 4/75 - 9/705799 4/75 - 9/705799 4/75 - 9/705799 4/75 - 9/707799 4/75 - 9/7077999 4/75 - 9/707799 4/75 - 9/7077999 4/75 - 9/7077999 4/75 - 9/	Kenworth	315576	970578	13201	6/17 - 11/29/1999	376	7/7 - 10/30/1999	188
315651 970578	Kenworth	315577	970578	13201	6/17 - 11/29/1999 5/16 - 7/31/2000	4890	7/7 - 10/30/1999	3048
316251 970578				Kenwort: 1320l Sub	Tota!	5306		326
318293 970578	Freightliner	315651	870578	1320	6/28 - 11/15/1999 4/25 - 7/25/2000	183	7/23 - 9/21/1999	105
316294 970578 1320 6728-11/23/1999 24 8/10 - 10/22/1999 24 8/10 - 10/22/1999 24 8/10 - 8/17/1999 22 8/10 - 8/17/1999 22 8/10 - 8/17/1999 22 8/10 - 8/17/1999 22 8/10 - 8/17/1999 22 8/10 - 8/17/1999 22 8/10 - 8/17/1999 22 8/10 - 8/17/1999 22 8/10 - 8/17/1999 22 8/10 - 8/17/1999 22 8/10 - 8/17/1999 22 8/10 - 8/17/1999 22 22 8/10 - 8/17/1999 22 22 22 22 22 22 22	Freightliner	318293	970578	1320	4729 - 7722/2000	99	8/3 - 10/28/1999	22
325032 970578 1320l 6/16 : 8/17/1999 22 8/10 · 8/17/1999 326440 970578 1320l 07/22/2000 10 07/07/1999 325444 970578 1320l 07/07/1999 1 08/17/1999 325661 970578 1320l 06/17/1999 1 08/17/1999 970580 Verticle Socket 77 · 8/27/99 311 77 · 8/27/1999 326839 Paccar Sub Total 8 8	Freightliner	318294	970578	1320	6/28 - 11/23/1999	24	8/10 - 10/22/1999	17
326440	Freightliner	325032	970578	13201	6/18 - 8/17/1999	22	8/10 - 8/17/1999	4
315650 970578 13201 077222000 10 077071999 1 0770711999 1 0770711999 1 0770711999 1 0817711999 1325444 970578 13201 061771999 1 081771	Freightliner	326440			11/17 - 12/20/99	Ø	Mag.	
325199 970578 13201 07/07/1999 1 07/07/1999 1 07/07/1999 1 08/17/1999	Freightliner	315650	970578	13201	07/22/2000	10	IIIFtaa	
325444 970578 1320 064771999 1 0847	Freightliner	325199	970578	13201	07/07/1999	=	07/07/1999	1
S26661 PT0578 Freigntliner 1320 Sub Total 311 326839 4 777 - 8/27/1999 326839 Paccar Sub Total 8 8 311 31	Freightliner	325444	970578	13201	08/17/1999		08/17/1999	
970580 Verticle Socket 7/7 - 8/27/1999 4 7/7 - 8/27/1999 326839 Paccar Sub Total 8 8	Freightliner	22000	8/00/8	Freightliner 13201 S	nh Total	311		150
326839	PACCAR	970580		Verticle Socket	7/7 - 8/27/99	4	7/7 - 8/27/1999	4
Paccar Sub Total	PACCAR	326839			05/24/2000	4		
				Paccar Sub Total	R PURSUAL CONTRACTOR SERVICE	8		4

11/05/2001

Freightliner Dates are Expansion above TRW's per Freightliner's request