GM CUSTOMER CARE AND AFTERSALES

DCS2472

URGENT - DISTRIBUTE IMMEDIATELY

September 27, 2010

Date:

Subject:	10282 - Safety Recall – Special Advisory Letter Engine Stall Due to PCM Failure
Models:	2005-2008 MY Pontiac Vibe Equipped with 1.8L MFI Engine (RPO LV6) and Two-Wheel Drive Transmission
То:	All GM Dealers (Except Saturn and HUMMER)
Attention:	General Manager, Service Manager, Parts Manager, Used Car Manager and Warranty Administrator
General Motors announced Safety Rector potential media and customer inqui	all 10282 on August 25, 2010 in order to prepare dealers ries.
That announcement message also contained the following statement:	
±	letter to all involved customers informing them of this e a future notice when parts become available to complete

The purpose of this message is to provide dealers with an advance copy of the special advisory

letter which will be mailed to all involved customers later today.

Please open the attached file to view or print the letter.

Specific vehicle information for this recall will not be available in the GWM–IVH (GMVIS2) application until the recall bulletin is released to dealers. The bulletin release date has not yet been determined.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Nothing in this message is intended to constitute an electronic signature unless a specific statement to the contrary is included in this message.

Confidentiality Note: This message is intended only for the person or entity to which it is addressed. It may contain confidential and/or privileged material. Any review, transmission, dissemination or other use, or taking of any action in reliance upon this message by persons or entities other than the intended recipient is prohibited and may be unlawful. If you received this message in error, please contact the sender and delete it from your computer.