VIN PATROPICAS DECEA	The vehicle is not available because: (please check the appropriate box)	SERVICE BULLETIN 443-446 • IMPORTANT SAFETY RECALL	Triumph Motorcycles (America) Ltd • Safety Recall Reply Form
----------------------	--	--	--

manipri violojojes (America) Eta - Salety Necali Nepiy I offi
SERVICE BULLETIN 443-446 • IMPORTANT SAFETY RECALL
The vehicle is not available because: (please check the appropriate box)
VIN SMTD00NS16J260519
☐ The vehicle has been written off ☐ The vehicle has been stolen
☐ The vehicle has been sold (please provide new owner details below if known)
Name
Address
City/State/Zip

Name	
Address	
City/State/Zip	
Email	

יסיי ואים שאנווצן נוופ נווות to complete and return this important safety recall document.

Please Detach Here

Detach the card

to us,

Filling out the car

Please help us u

Bike has been scr

Thank you for han.
Triumph

****In Canada]

postage

BUSINESS REPLY MAIL

POSTAGE WILL BE PAID BY ADDRESSEE

TRIUMPH MOTORCYCLES
385 INTERNATIONAL PARK STE 100
NEWNAN GA 30265-9910



IMPORTANT SAFETY RECALL RM2012/019

REPLACEMENT OF THE REGULATOR RECTIFIER FOR STREET TRIPLE AND DAYTONA 675

Dear Triumph,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act

VIN:

Triumph has decided that a defect which relates to motor vehicle safety exists in certain model year 2006-2009 Street Triple, Street Triple R, and Daytona 675 motorcycles. The regulator/rectifier can overheat and prevent the motorcycle from charging. Once the battery is fully discharged, the motorcycle may stall. If the motorcycle stalls, there is an increased risk of a crash leading to personal injury.

To correct this condition, your dealer will replace the regulator rectifier. The service and parts will be provided free of charge. This work will take about ½ hour to complete however, additional time may be required depending on how dealer appointments are scheduled and processed. We urge you to contact your local Triumph dealer immediately to arrange an early appointment with the service department.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

Should you need to discuss any aspect of this please contact your dealer who will be able to answer any enquiries. If necessary, you can of course call our Customer Service Department at Triumph at the address below.

We regret any inconvenience that this action may cause you. However, we are concerned about your safety. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time:

- For the our US Customers: You may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.
- For our Canadian Customers: If after contacting your dealer and/or Manufacturer Customer Service you have additional questions with regards to this recall, you may contact Transport Canada Road Safety, 80 rue Noël, Gatineau, Quebec J8Z 0A1. Or call 1-800-333-0510.

Recall Coordinator

Scott H. Callander



NEWNAN, GEORGIA 30265, USA

SAFETY RECALL SAFETY RECALLON

PRSRT ST US POSTAI PAID MARIETTA, PERMIT NO.