

**Part 573 Safety Recall Report****15V-455****Manufacturer Name :** Tracker Marine L.L.C.**Submission Date :** JUL 17,2015**NHTSA Recall No. :** 15V-455**Manufacturer Recall No. :** TS-0031**Manufacturer Information :**

Manufacturer Name : Tracker Marine L.L.C.

Address : 2500 E. Kearney  
Springfield MO 65898

Company phone : 417-873-4555

**Population :**

Number of potentially involved : 346

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2016-2016 Trailstar Tahoe 400, 450,500, 550

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Tahoe boat trailer models 400, 450, 500, 550

Serial number range by model listed below.

Production Dates : MAR 23, 2015 - JUN 24, 2015

**VIN (Vehicle Identification Number) Range**Begin : 4TM15AH10GB001168                      End : 4TM15AH1XGB001243                       Not sequential VINsBegin : 4TM15BH10GB001077                      End : 4TM15BH1XGB001152                       Not sequential VINsBegin : 4TM15FK10GB001113                      End : 4TM15FK1XGB001183                       Not sequential VINsBegin : 4TM15GK10GB001036                      End : 4TM15GK1XGB001111                       Not sequential VINs**Description of Noncompliance :**

Description of the Noncompliance : Tire/wheel assemblies of incorrect load range were installed on affected models. Load range "D" tire/wheels are specified for the affected models. Load range "C" tires were installed on the affected units.

Please note the load range "C" tire/wheel from the supplier is NOT a defective component.

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : Potential failure of tire due to possibly exceeding load rating of the tire.

Description of the Cause : The noncompliant load range "C" tire/wheel was mistakenly purchased for the load range "D" application.  
Identification of Any Warning that can Occur : Tires may displays signs of accelerated wear or run hotter than normal.

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

6/24/2015 Incorrect load range tires observed being installed in production process.

**Description of Remedy :**

Description of Remedy Program : The recall condition is the affected trailers have load range "C" tires/wheels installed. Replacement of tires/wheels with load range "D" tires/wheels is the remedy.

How Remedy Component Differs from Recalled Component : The incorrect tires display load range "C" on the sidewall. The correct tire/wheel assemblies display load range "D" on the sidewall.

Identify How/When Recall Condition was Corrected in Production : All affected tires/wheels and trailers were identified and quarantined upon discovery of condition on 6/24/15. All affected trailers will have the tires/wheels replaced with load range "D" tires/wheels. The field remedy is identical to remedy in production. All inventory of new tires/wheels in the affected date range were quarantined and returned to the supplier.

All trailers in Tracker Marine Group inventory will be inspected before shipment to ensure all affected trailers have the tires/wheels replaced with load range "D" tires/wheels.

**Recall Schedule :**

Description of Recall Schedule : Recall notification to be published to TracNet – online Dealer Information Management Site once this report has been submitted.

Three – four days after NHTSA approval – Recall notification letter to warranty registered consumers to be mailed.

Planned Dealer Notification Date : JUL 20, 2015 - JUL 20, 2015

Planned Owner Notification Date : JUL 27, 2015 - JUL 27, 2015

\* NR - Not Reported